


## **PROBLEM SUMMARY**



Machine Id **10446** Component **Diesel Engine** Fluid **PETRO CANADA DURON SHP 15W40 (8 GAL)** 

## COMPONENT CONDITION SUMMARY



#### RECOMMENDATION

We advise that you check for the source of the coolant leak. Check for low coolant level. Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS								
Sample Status				SEVERE	SEVERE	SEVERE		
Sodium	ppm	ASTM D5185m		<u> </u>	<u> </u>	<u> </u>		
Potassium	ppm	ASTM D5185m	>20	<b>A</b> 3798	<u> </u>	🔺 1128		
Glycol	%	*ASTM D2982		0.20	0.20	0.20		

Customer Id: GFL018 Sample No.: GFL0089972 Lab Number: 06002778 Test Package: FLEET



To manage this report scan the QR code

*To discuss the diagnosis or test data:* Doug Bogart +1 (800)237-1369 x4016 <u>dougb@wearcheckusa.com</u>

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS							
Action	Status	Date	Done By	Description			
Change Fluid			?	Oil and filter change at the time of sampling has been noted.			
Change Filter			?	Oil and filter change at the time of sampling has been noted.			
Resample			?	We recommend an early resample to monitor this condition.			
Check Glycol Access			?	We advise that you check for the source of the coolant leak.			

## HISTORICAL DIAGNOSIS



## 04 Oct 2023 Diag: Doug Bogart

We advise that you check for the source of the coolant leak. Check for low coolant level. Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition. The copper level is abnormal. In the absence of other significant wear metals, suspect copper due to sources other than wear (i.e. cooling core). All other component wear rates are normal. Sodium and/or potassium levels are high. Test for glycol is positive. The BN result indicates that there is suitable alkalinity remaining in the oil.



view report

#### GLYCOL



# 25 Apr 2023 Diag: Jonathan Hester

We advise that you check for the source of the coolant leak. Check for low coolant level. Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition.All component wear rates are normal. Sodium and/or potassium levels are high. Test for glycol is positive. The BN result indicates that there is suitable alkalinity remaining in the oil.

#### 07 Apr 2023 Diag: Wes Davis



We advise that you check for the source of the coolant leak. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition.All component wear rates are normal. Test for glycol is positive. There is a high concentration of glycol present in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The oil is no longer serviceable due to the presence of contaminants.







## **OIL ANALYSIS REPORT**

Sample Rating Trend

GLYCOL

#### Machine Id 10446

Component

**Diesel Engine** Fluid

## PETRO CANADA DURON SHP 15W40 (8 GAL)

## DIAGNOSIS

#### Recommendation

We advise that you check for the source of the coolant leak. Check for low coolant level. Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

#### Wear

All component wear rates are normal.

#### Contamination

Sodium and/or potassium levels are high. Test for glycol is positive.

#### Fluid Condition

The BN result indicates that there is suitable alkalinity remaining in the oil.





~=)		g2014 Apr201	15 Feb2016 Oct2016	Jul2017 Feb2019 Jan2021 Aug20	122 Oct2023	
SAMPLE INFOF	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GFL0089972	GFL0080537	GFL0074434
Sample Date		Client Info		07 Nov 2023	04 Oct 2023	25 Apr 2023
Machine Age	hrs	Client Info		59145	59145	59145
Oil Age	hrs	Client Info		59145	59145	59145
Oil Changed		Client Info		Changed	Changed	Changed
Sample Status				SEVERE	SEVERE	SEVERE
CONTAMINAT	TION	method	limit/base	current	history1	history2
Fuel		WC Method	>3.0	<1.0	<1.0	<1.0
Water		WC Method	>0.2	NEG	NEG	NEG
WEAR METAL	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>75	32	33	15
Chromium	ppm	ASTM D5185m	>5	1	2	<1
Nickel	ppm	ASTM D5185m	>4	<1	<1	0
Titanium	ppm	ASTM D5185m	>2	<1	<1	0
Silver	ppm	ASTM D5185m	>2	0	0	0
Aluminum	ppm	ASTM D5185m	>15	5	5	2
Lead	ppm	ASTM D5185m	>25	1	<1	0
Copper	ppm	ASTM D5185m		92	<u> </u>	9
Tin	ppm	ASTM D5185m	>4	<1	<1	0
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	2	1	2
Barium	ppm	ASTM D5185m	0	0	0	0
Molybdenum	ppm	ASTM D5185m	60	66	72	63
Manganese	ppm	ASTM D5185m	0	<1	<1	<1
Magnesium	ppm	ASTM D5185m	1010	904	872	948
Calcium	ppm	ASTM D5185m	1070	988	1009	1090
Phosphorus	ppm	ASTM D5185m	1150	941	942	1038
Zinc	ppm	ASTM D5185m	1270	1213	1177	1296
Sulfur	ppm	ASTM D5185m	2060	2844	2911	3333
CONTAMINAN	NTS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	17	17	5
Sodium	ppm	ASTM D5185m		<u> </u>	<u> </u>	<u> </u>
Potassium	ppm	ASTM D5185m	>20	<b>A</b> 3798	<b>4</b> 168	<u>▲</u> 1128
Glycol	%	*ASTM D2982		0.20	0.20	0.20
INFRA-RED		method	limit/base	current	history1	history2
Coat %	%	*ASTM D7844	>6	0.3	0.3	0.2
Soot %						
Nitration	Abs/cm	*ASTM D7624	>20	12.6	12.3	7.5

FLUID DEGRAD	DATION	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	16.4	16.3	15.2
Base Number (BN)	mg KOH/g	ASTM D2896	9.8	12.3	12.1	10.7



# **OIL ANALYSIS REPORT**





VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
FLUID PROPE	RTIES	method	limit/base	current	history1	history2
Visc @ 100°C	cSt	ASTM D445	15.4	14.4	14.4	14.4
GRAPHS						

Ferrous Alloys


120


Jan31/21

Aug 19/22

eb25/19

VIOLIA






Received

Diagnosed

: 22 Nov 2023

Diagnostician : Doug Bogart



4621 Marracco Drive Hope Mills, NC US 28348 Contact: Robert Carter robert.carter@gflenv.com T: (910)596-1170 F:



Aug14/14

Apr22/1

eb17/16

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Laboratory

Sample No.

Lab Number

Unique Number

Test Package : FLEET

: GFL0089972

:06002778

: 10736540

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Certificate L2367

Submitted By: Robert Carter