

PROBLEM SUMMARY


Sample Rating Trend FUEL



Machine Id
4508M
Component
Diesel Engine

PETRO CANADA DURON SHP 15W40 (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS							
Sample Status				ABNORMAL	ABNORMAL	NORMAL	
Fuel	%	ASTM D3524	>3.0	5.8	△ 6.8	<1.0	

Customer Id: GFL415 Sample No.: GFL0101525 Lab Number: 06010490 Test Package: FLEET

To manage this report scan the QR code

To discuss the diagnosis or test data: Wes Davis +1 905-569-8600 x223 wesd@wearcheck.ca

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Resample			?	We recommend an early resample to monitor this condition.

HISTORICAL DIAGNOSIS

02 May 2023 Diag: Wes Davis





The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition. All component wear rates are normal. There is a moderate amount of fuel present in the oil. Tests confirm the presence of fuel in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. Fuel is present in the oil and is lowering the viscosity. The oil is no longer serviceable due to the presence of contaminants.



13 Dec 2022 Diag: Wes Davis

NORMAL



Resample at the next service interval to monitor. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.



05 Oct 2022 Diag: Jonathan Hester

FUEL




Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. Light fuel dilution occurring. The oil viscosity is lower than normal. The BN result indicates that there is suitable alkalinity remaining in the oil. Confirm oil type.





OIL ANALYSIS REPORT

Samp





Machine Id
4508M
Component
Diesel Engine
Fluid

PETRO CANADA DURON SHP 15W40 (--- GAL)

DIAGNOSIS

Recommendation

The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

Wear

All component wear rates are normal.

Contamination

There is a moderate amount of fuel present in the oil. Tests confirm the presence of fuel in the oil.


Fluid Condition


The BN result indicates that there is suitable alkalinity remaining in the oil. The oil is no longer serviceable due to the presence of contaminants.


0.4451.5.1450.54	4471011	Junzozi P	Aug2021 Nov2021 Feb202			
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GFL0101525	GFL0068668	GFL0064053
Sample Date		Client Info		15 Nov 2023	02 May 2023	13 Dec 2022
Machine Age	hrs	Client Info		11828	10559	9916
Oil Age	hrs	Client Info		10559	9916	9304
Oil Changed		Client Info		Changed	Changed	Changed
Sample Status				ABNORMAL	ABNORMAL	NORMAL
CONTAMINATI	ION	method	limit/base	current	history1	history2
Glycol		WC Method		NEG	NEG	NEG
WEAR METALS	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>90	9	21	23
Chromium	ppm	ASTM D5185m	>20	<1	<1	1
Nickel	ppm	ASTM D5185m	>2	0	0	<1
Titanium	ppm	ASTM D5185m	>2	<1	0	<1
Silver	ppm	ASTM D5185m	>2	0	0	0
Aluminum	ppm	ASTM D5185m	>20	3	3	3
Lead	ppm	ASTM D5185m	>40	0	0	0
Copper	ppm	ASTM D5185m	>330	2	<1	1
Tin	ppm	ASTM D5185m	>15	0	<1	<1
Vanadium	ppm	ASTM D5185m		<1	0	<1
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	<1	<1	4
Barium	ppm	ASTM D5185m	0	0	0	0
Molybdenum	ppm	ASTM D5185m	60	52	54	58
Manganese	ppm	ASTM D5185m	0	<1	<1	<1
Magnesium	ppm	ASTM D5185m	1010	831	778	908
Calcium	ppm	ASTM D5185m	1070	968	951	1029
Phosphorus	ppm	ASTM D5185m	1150	913	903	977
Zinc	ppm	ASTM D5185m	1270	1142	1081	1220
Sulfur	ppm	ASTM D5185m	2060	2611	2438	3177
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m		4	5	6
Sodium	ppm	ASTM D5185m		4	2	9
Potassium	ppm	ASTM D5185m	>20	4	6	2
Fuel	%	ASTM D3524	>3.0	<u>^</u> 5.8	<u></u> 6.8	<1.0
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>6	0.4	0.5	0.8
Nitration	Abs/cm	*ASTM D7624	>20	7.6	8.6	11.6
Sulfation	Abs/.1mm	*ASTM D7415	>30	19.1	18.0	23.1
FLUID DEGRAD	OATION	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	15.1	15.8	20.4
Oxidation Base Number (BN)	Abs/.1mm mg KOH/g	*ASTM D7414 ASTM D2896		15.1 8.6	15.8 6.3	20.4 8.6



OIL ANALYSIS REPORT










VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG


FLUID PROPE	RIIES	method	iiiiii/base	current	riistory i	nistoryz
Visc @ 100°C	cSt	ASTM D445	15.4	12.7	▲ 12.2	14.2

GRAPHS













Laboratory Sample No. Lab Number **Unique Number**

: 10749634

: GFL0101525 : 06010490

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received

: 17 Nov 2023 Diagnosed

: 20 Nov 2023 Diagnostician : Wes Davis

Test Package : FLEET (Additional Tests: PercentFuel) To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

GFL Environmental - 415 - Michigan East

6200 Elmridge Sterling Heights, MI US 48313 Contact: Frank Wolak fwolak@gflenv.com T: (586)825-9514

Submitted By: Frank Wolak