

PROBLEM SUMMARY







Machine Id 723031-303001 Component Transmission Fluid NOT GIVEN (--- GAL)

COMPONENT CONDITION SUMMARY

No relevant graphs to display

RECOMMENDATION

Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

PROBLEMATION	PROBLEMATIC TEST RESULTS							
Sample Status				ABNORMAL				
Debris	scalar	*Visual	NONE	▲ MODER				

Customer Id: GFL837 Sample No.: GFL0098613 Lab Number: 06011890 Test Package: FLEET



To manage this report scan the QR code

To discuss the diagnosis or test data: Jonathan Hester +1 919-379-4092 x4092 jhester@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Change Fluid			?	Oil and filter change at the time of sampling has been noted.		
Change Filter			?	Oil and filter change at the time of sampling has been noted.		

HISTORICAL DIAGNOSIS



OIL ANALYSIS REPORT

Sample Rating Trend

VIS DEBRIS



723031-303001

Component

Transmission

NOT GIVEN (--- GAL)





DIAGNOSIS

Recommendation

Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

Moderate concentration of visible dirt/debris present in the fluid.


Fluid Condition

The condition of the fluid is acceptable for the time in service.

				Nov2023		
CAMPLE INCODE	AATION					111
SAMPLE INFORI	VIATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GFL0098613		
Sample Date		Client Info		08 Nov 2023		
Machine Age	hrs	Client Info		19807		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		Changed		
Sample Status				ABNORMAL		
CONTAMINAT	ION	method	limit/base	current	history1	history2
Water		WC Method	>0.1	NEG		
WEAR METAL	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	55		
Chromium	ppm	ASTM D5185m	>10	0		
Nickel	ppm	ASTM D5185m		0		
Titanium	ppm	ASTM D5185m		<1		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>50	19		
Lead	ppm	ASTM D5185m	>50	2		
Copper	ppm	ASTM D5185m	>200	10		
Tin	ppm	ASTM D5185m	>10	1		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		70		
Barium	ppm	ASTM D5185m		0		
Molybdenum	ppm	ASTM D5185m		<1		
Manganese	ppm	ASTM D5185m		<1		
Magnesium	ppm	ASTM D5185m		8		
Calcium	ppm	ASTM D5185m		130		
Phosphorus	ppm	ASTM D5185m		198		
Zinc	ppm	ASTM D5185m		4		
Sulfur	ppm	ASTM D5185m		1765		
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	13		
Sodium	ppm	ASTM D5185m		8		
Potassium	ppm	ASTM D5185m	>20	3		
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE		
Yellow Metal	scalar	*Visual	NONE	NONE		
Precipitate	scalar	*Visual	NONE	NONE		
Silt	scalar	*Visual	NONE	NONE		
Debris	scalar	*Visual	NONE	▲ MODER		
Sand/Dirt	scalar	*Visual	NONE	NONE		
Appearance	scalar	*Visual	NORML	NORML		
Odor	scalar	*Visual	NORML	NORML		
Emulsified Water	scalar	*Visual	>0.1	NEG		
Free Water	scalar	*Visual		NEG		



OIL ANALYSIS REPORT





Laboratory Sample No. Lab Number Unique Number

: GFL0098613 : 06011890

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received

Diagnosed Diagnostician : Jonathan Hester

: 20 Nov 2023 : 29 Nov 2023

GFL Environmental - 837 - Harrison TS 22820 S State Route 291 Harrisonville, MO US 64701

: 10751034 Test Package : FLEET (Additional Tests: FT-IR, FuelDilution, KV100, PercentFuel, TBIContact: BRYAN SWANSON bryanswanson@gflenv.com To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Report Id: GFL837 [WUSCAR] 06011890 (Generated: 11/29/2023 17:03:45) Rev: 1

Contact/Location: BRYAN SWANSON - GFL837

T:

F: