

PROBLEM SUMMARY

Sample Rating Trend

VISCOSITY






Machine Id 413116 Component Diesel Engine

PETRO CANADA DURON SHP 15W40 (--- QTS)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

No corrective action is recommended at this time. Resample at the next service interval to monitor.

DROB!	EMATIC:	TEST RESU	II TQ
FNODL		I EO I NEOL	JLIO

Sample Status				ATTENTION	ATTENTION	ATTENTION
Visc @ 100°C	cSt	ASTM D445	15.4	11.7	<u>▲</u> 11.7	<u>▲</u> 11.4

Customer Id: GFL836 Sample No.: GFL0098660 Lab Number: 06013030 Test Package: FLEET



To manage this report scan the QR code

To discuss the diagnosis or test data: Sean Felton +1 919-379-4092 sfelton@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS

27 Oct 2023 Diag: Sean Felton

VISCOSITY



No corrective action is recommended at this time. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. The BN result indicates that there is suitable alkalinity remaining in the oil. Confirm oil type.



06 Oct 2023 Diag: Don Baldridge

VISCOSITY



Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. The BN result indicates that there is suitable alkalinity remaining in the oil. Confirm oil type.



12 Jul 2023 Diag: Don Baldridge

VISCOSITY



Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. The BN result indicates that there is suitable alkalinity remaining in the oil. Confirm oil type.





OIL ANALYSIS REPORT


Sample Rating Trend

VISCOSITY



Machine Id 413116 Component **Diesel Engine**

PETRO CANADA DURON SHP 15W40 (--- QTS)





DIAGNOSIS

Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

There is no indication of any contamination in the oil.


▲ Fluid Condition


The oil viscosity is lower than normal. The BN result indicates that there is suitable alkalinity remaining in the oil. Confirm oil type.

N SHP 15W40 (Q15)	Apr2023	Jul2023	Oct2023 Oct2023	Nov2023	
SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GFL0098660	GFL0098645	GFL0093719
Sample Date		Client Info		15 Nov 2023	27 Oct 2023	06 Oct 2023
Machine Age	hrs	Client Info		1951	1865	1693
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	Not Changd	Changed
Sample Status				ATTENTION	ATTENTION	ATTENTION
CONTAMINAT	ION	method	limit/base	current	history1	history2
Fuel		WC Method	>3.0	<1.0	<1.0	<1.0
Water		WC Method	>0.2	NEG	NEG	NEG
Glycol		WC Method		NEG	NEG	NEG
WEAR METAL	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>120	8	4	11
Chromium	ppm	ASTM D5185m	>20	<1	0	<1
Nickel	ppm	ASTM D5185m	>5	0	<1	0
Titanium	ppm	ASTM D5185m	>2	<1	0	0
Silver	ppm	ASTM D5185m	>2	<1	<1	1
Aluminum	ppm	ASTM D5185m	>20	3	3	5
Lead	ppm	ASTM D5185m	>40	<1	<1	0
Copper	ppm	ASTM D5185m	>330	70	61	301
Tin	ppm	ASTM D5185m	>15	<1	<1	1
Vanadium	ppm	ASTM D5185m		<1	<1	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	31	43	22
Barium	ppm	ASTM D5185m	0	0	0	0
Molybdenum	ppm	ASTM D5185m	60	56	58	62
Manganese	ppm	ASTM D5185m	0	<1	<1	<1
Magnesium	ppm	ASTM D5185m	1010	1096	1081	1012
Calcium	ppm	ASTM D5185m	1070	804	809	838
Phosphorus	ppm	ASTM D5185m	1150	948	1028	938
Zinc	ppm	ASTM D5185m	1270	1211	1290	1139
Sulfur	ppm	ASTM D5185m	2060	3088	3453	2752
CONTAMINAN	ITS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	5	5	7
Sodium	ppm	ASTM D5185m		4	2	4
Potassium	ppm	ASTM D5185m	>20	6	6	13
rotassium						
INFRA-RED		method	limit/base	current	history1	history2
	%	method *ASTM D7844	limit/base >4	current 0.2	history1 0.1	history2 0.3
INFRA-RED	% Abs/cm					
INFRA-RED Soot % Nitration		*ASTM D7844	>4	0.2	0.1	0.3
INFRA-RED Soot %	Abs/cm Abs/.1mm	*ASTM D7844 *ASTM D7624 *ASTM D7415	>4 >20	0.2 8.8	0.1 7.6	0.3 9.6 20.5
INFRA-RED Soot % Nitration Sulfation	Abs/cm Abs/.1mm	*ASTM D7844 *ASTM D7624 *ASTM D7415	>4 >20 >30	0.2 8.8 20.3	0.1 7.6 19.7	9.6



OIL ANALYSIS REPORT








VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	LIGHT	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG


FLUID FROF	LHILS	memou	IIIIII/Dase	Current	HISTORY	HISTOLY
Visc @ 100°C	cSt	ASTM D445	15.4	<u> </u>	<u> 11.7</u>	<u> </u>

GRAPHS











Certificate L2367

Laboratory Sample No. Lab Number **Unique Number**

: GFL0098660 : 06013030 : 10752174 Test Package : FLEET

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 20 Nov 2023 Diagnosed Diagnostician : Sean Felton

: 22 Nov 2023

GFL Environmental - 836 - Kansas City Hauling

7801 East Truman Road Kansas City, MO US 64126

Contact: Robert Hart rhart@gflenv.com T: (580)461-1509

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)