

PROBLEM SUMMARY

Sample Rating Trend

SEDIMENT



928091-260348

Component **Transmission**

NOT GIVEN (--- GAL)

COMPONENT CONDITION SUMMARY

No relevant graphs to display

RECOMMENDATION

Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS										
Sample Status				ABNORMAL						
Silt	scalar	*Visual	NONE	▲ MODER						

Customer Id: GFL837 Sample No.: GFL0098576 Lab Number: 06014682 Test Package: FLEET



To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS


There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS



OIL ANALYSIS REPORT

Sample Rating Trend



SEDIMENT



928091-260348

Component

Transmission

NOT GIVEN (--- GAL)

DIAGNOSIS

Recommendation

Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

There is a moderate amount of visible silt present in the sample.


Fluid Condition


The condition of the fluid is acceptable for the time in service.

				Nov2023		
0.11.151.5.11.150.51						
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GFL0098576		
Sample Date		Client Info		06 Nov 2023		
Machine Age	hrs	Client Info		13546		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				ABNORMAL		
CONTAMINATI	ION	method	limit/base	current	history1	history2
Water		WC Method	>0.1	NEG		
WEAR METALS	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	96		
Chromium	ppm	ASTM D5185m	>10	<1		
Nickel	ppm	ASTM D5185m		<1		
Titanium	ppm	ASTM D5185m		<1		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>50	19		
Lead	ppm	ASTM D5185m	>50	6		
Copper	ppm	ASTM D5185m	>200	9		
Tin	ppm	ASTM D5185m	>10	2		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		<1		
ADDITIVES		method	limit/base	ourront	hiotonyl	hiotory
ADDITIVES		method	IIIIII/Dase	current	history1	history2
Boron	ppm	ASTM D5185m		85		
Barium	ppm	ASTM D5185m		0		
Molybdenum	ppm	ASTM D5185m		<1		
Manganese	ppm	ASTM D5185m		<1		
Magnesium	ppm	ASTM D5185m		3		
Calcium	ppm	ASTM D5185m		129		
Phosphorus	ppm	ASTM D5185m		241		
Zinc	ppm	ASTM D5185m		0		
Sulfur	ppm	ASTM D5185m		1588		
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	7		
Sodium	ppm	ASTM D5185m		3		
Potassium	ppm	ASTM D5185m	>20	2		
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE		
Yellow Metal	scalar	*Visual	NONE	NONE		
Precipitate	scalar	*Visual	NONE	NONE		
Silt	scalar	*Visual	NONE	▲ MODER		
Debris	scalar	*Visual	NONE	NONE		
Sand/Dirt	scalar	*Visual	NONE	NONE		
Appearance	scalar	*Visual	NORML	NORML		
Odor	scalar	*Visual	NORML	NORML		
Emulsified Water	scalar	*Visual	>0.1	NEG		
Free Water	scalar	*Visual		NEG		





OIL ANALYSIS REPORT






GRAPHS









Certificate L2367

Laboratory Sample No. Lab Number

Unique Number : 10753826 Test Package : FLEET

: GFL0098576 : 06014682

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 21 Nov 2023 Diagnosed : 24 Nov 2023 Diagnostician : Don Baldridge

GFL Environmental - 837 - Harrison TS

22820 S State Route 291 Harrisonville, MO US 64701

Contact: BRYAN SWANSON bryanswanson@gflenv.com

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Contact/Location: BRYAN SWANSON - GFL837

T:

F: