


PROBLEM SUMMARY

Sample Rating Trend




921047-260381

Component **Diesel Engine**

PETRO CANADA DURON SHP 15W40 (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

No corrective action is recommended at this time. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS								
Sample Status			ATTENTION	ATTENTION	ATTENTION			
Sodium	ppm	ASTM D5185m	<u> </u>	△ 168	△ 136			

Customer Id: GFL837 Sample No.: GFL0098590 Lab Number: 06028410 Test Package: FLEET



To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS

07 Nov 2023 Diag: Sean Felton

GLYCOL



No corrective action is recommended at this time. Resample at the next service interval to monitor. All component wear rates are normal. Sodium and/or potassium levels are high. Test for glycol is negative. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.



16 Oct 2023 Diag: Jonathan Hester

GLYCOL



No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. Sodium and/or potassium levels are high. Test for glycol is negative. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.



DIRT



15 Sep 2023 Diag: Jonathan Hester


We advise that you check for the source of the coolant leak. Check for low coolant level. We advise that you check the air filter, air induction system, and any areas where dirt may enter the component. Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition. All component wear rates are normal. Sodium and/or potassium levels are high. Elemental levels of silicon (Si) and aluminum (Al) indicate alumina-silicate (coarse dirt) ingress. The BN result indicates that there is suitable alkalinity remaining in the oil





OIL ANALYSIS REPORT

Sample Rating Trend



GLYCOL



921047-260381

Component

Diesel Engine

PETRO CANADA DURON SHP 15W40 (--- GAL)

DIAGNOSIS

Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

Sodium and/or potassium levels are high. Test for glycol is negative.


▲ Fluid Condition


The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.


GAL)		May2019 J	an2023 Mar2023 Jun20	23 Sep 2023 Oct 2023 Nov 2023	Nov2023	
SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GFL0098590	GFL0098578	GFL0093689
Sample Date		Client Info		28 Nov 2023	07 Nov 2023	16 Oct 2023
Machine Age	hrs	Client Info		0	6600	6492
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	Not Changd	Not Changd
Sample Status				ATTENTION	ATTENTION	ATTENTION
CONTAMINAT	ION	method	limit/base	current	history1	history2
Fuel		WC Method	>5	<1.0	<1.0	<1.0
Water		WC Method	>0.2	NEG	NEG	NEG
WEAR METAL	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>100	13	13	7
Chromium	ppm	ASTM D5185m	>20	<1	<1	<1
Nickel	ppm	ASTM D5185m	>4	0	0	<1
Titanium	ppm	ASTM D5185m		<1	<1	<1
Silver	ppm	ASTM D5185m	>3	0	0	0
Aluminum	ppm	ASTM D5185m	>20	4	5	2
Lead	ppm	ASTM D5185m	>40	0	0	<1
Copper	ppm	ASTM D5185m	>330	2	2	2
Tin	ppm	ASTM D5185m	>15	0	0	0
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	<1	<1
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	5	6	6
Barium	ppm	ASTM D5185m	0	6	<1	3
Molybdenum	ppm	ASTM D5185m	60	67	77	66
Manganese	ppm	ASTM D5185m	0	0	0	0
Magnesium	ppm	ASTM D5185m	1010	911	1115	903
Calcium	ppm	ASTM D5185m	1070	1100	1199	1057
Phosphorus	ppm	ASTM D5185m	1150	1005	1172	965
Zinc	ppm	ASTM D5185m	1270	1194	1420	1208
Sulfur	ppm	ASTM D5185m	2060	3023	4343	3192
CONTAMINAN	ITS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	8	9	7
Sodium	ppm	ASTM D5185m		<u> </u>	<u>▲</u> 168	▲ 136
Potassium	ppm	ASTM D5185m	>20	7	8	4
Glycol	%	*ASTM D2982		NEG	NEG	NEG
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	0.5	0.4	0.2
Nitration	Abs/cm	*ASTM D7624	>20	7.0	6.3	5.6
Sulfation	Abs/.1mm	*ASTM D7415	>30	19.4	19.1	18.3
FLUID DEGRAI	DATION	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	14.5	14.0	13.6
Base Number (BN)	mg KOH/g	ASTM D2896	9.8	8.7	8.8	9.1
()	0 - 0					



OIL ANALYSIS REPORT










VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	LIGHT	LIGHT
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG


FLUID PHOP	ELLIES	memod	IIIIII/Dase	Current	HISTORY	HISTORYZ
Visc @ 100°C	cSt	ASTM D445	15.4	13.9	14.0	14.1

GRAPHS













Certificate L2367

Laboratory Sample No. Lab Number Unique Number

: GFL0098590 : 06028410 : 10778201

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 07 Dec 2023 Diagnosed

: 10 Dec 2023 Diagnostician : Don Baldridge

Test Package : FLEET (Additional Tests: Glycol) To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

GFL Environmental - 837 - Harrison TS

22820 S State Route 291 Harrisonville, MO US 64701

Contact: BRYAN SWANSON bryanswanson@gflenv.com

T:

F: Contact/Location: BRYAN SWANSON - GFL837