

OIL ANALYSIS REPORT

Sample Rating Trend

WATER



DIAGNOSIS

Contamination

Fluid Condition

Wear

oil

service.

Recommendation

No corrective action is recommended at this time.

Resample at the next service interval to monitor. (

Customer Sample Comment: PM-2 sampled fluid)

There is a light concentration of water present in the


The condition of the oil is acceptable for the time in

All component wear rates are normal.

KEMP QUARRIES / BCS - MILL CREEK [68018] WL087 Componen


Rear Left Final Drive


PETRO CANADA PRODURO TO-4 SAE 50 (--- GAL)





OIL ANALYSIS REPORT





Certificate L2367