


PROBLEM SUMMARY


Walgreens - Tractor [Walgreens - Tractor] 136A624213


Diesel Engine


PETRO CANADA DURON SHP 10W30 (11 GAL)



COMPONENT CONDITION SUMMARY







RECOMMENDATION

Oil and filter change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS

_			_		
Sample Status				ABNORMAL	
Copper	ppm	ASTM D5185m	>150	^ 206	

Customer Id: TSV1369 Sample No.: PCA0106606 Lab Number: 06035662 Test Package: FLEET

To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Change Fluid			?	Oil and filter change at the time of sampling has been noted.		
Change Filter			?	Oil and filter change at the time of sampling has been noted.		

HISTORICAL DIAGNOSIS




OIL ANALYSIS REPORT

Walgreens - Tractor [Walgreens - Tractor] 136A624213

Diesel Engine

PETRO CANADA DURON SHP 10W30 (11 GAL)



DIAGNOSIS

Recommendation

Oil and filter change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor.

Wear

The copper level is abnormal. In the absence of other significant wear metals, suspect copper due to sources other than wear (i.e. cooling core). All other metal levels are typical for a new component breaking in.

Contamination

Elevated aluminum (Al) and/or lead (Pb) and potassium (K) levels in your metals analysis are likely a result of solder flux release into the lubricant and is common on new equipment/components. No other contaminants were detected in the oil.


Fluid Condition

The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service.

GAL)				Dec2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0106606		
Sample Date		Client Info		07 Dec 2023		
Machine Age	mls	Client Info		64035		
Oil Age	mls	Client Info		50000		
Oil Changed		Client Info		Changed		
Sample Status				ABNORMAL		
CONTAMINAT	ION	method	limit/base	current	history1	history2
Fuel		WC Method	>5	<1.0		
Water		WC Method	>0.2	NEG		
Glycol		WC Method		NEG		
WEAR METAL	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>80	77		
Chromium	ppm	ASTM D5185m	>5	6		
Nickel	ppm	ASTM D5185m	>2	2		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m	>3	0		
Aluminum	ppm	ASTM D5185m	>30	267		
Lead	ppm	ASTM D5185m	>30	4		
Copper	ppm	ASTM D5185m	>150	<u>^</u> 206		
Tin	ppm	ASTM D5185m	>5	6		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	2	24		
Barium	ppm	ASTM D5185m	0	0		
Molybdenum	ppm	ASTM D5185m	50	41		
Manganese	ppm	ASTM D5185m	0	4		
Magnesium	ppm	ASTM D5185m	950	580		
Calcium	ppm	ASTM D5185m	1050	1853		
Phosphorus	ppm	ASTM D5185m	995	776		
Zinc	ppm	ASTM D5185m	1180	905		
Sulfur	ppm	ASTM D5185m	2600	1724		
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>20	10		
Sodium	ppm	ASTM D5185m		7		
Potassium	ppm	ASTM D5185m	>20	563		
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	0.6		
Nitration	Abs/cm	*ASTM D7624	>20	12.0		
Sulfation	Abs/.1mm	*ASTM D7415	>30	23.9		
FLUID DEGRAD	OATION	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	29.6		
Base Number (BN)	mg KOH/g	ASTM D2896		5.0		



OIL ANALYSIS REPORT







Certificate L2367

Sample No. Lab Number **Unique Number** Test Package : FLEET

: 10790891

To discuss this sample report, contact Customer Service at 1-800-237-1369.

: PCA0106606 Recieved : 06035662

: 15 Dec 2023 : 19 Dec 2023 Diagnosed Diagnostician : Don Baldridge 710 Ovilla Road

Waxahachie, TX US 75167 Contact: Robert Beal rbeal@transervice.com

T: (972)923-9928

F: (972)923-9919

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Report Id: TSV1369 [WUSCAR] 06035662 (Generated: 12/19/2023 10:42:30) Rev: 1

Contact/Location: Robert Beal - TSV1369