

PROBLEM SUMMARY

Sample Rating Trend


FUEL


Machine Id **427092-402367**

Component **Diesel Engine**

PETRO CANADA DURON SHP 15W40 (--- GAL)

COMPONENT CONDITION SUMMARY





RECOMMENDATION

We advise that you check the fuel injection system. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

PROBLEMATI	C TES	T RESULT	S			
Sample Status				SEVERE	SEVERE	SEVERE
Fuel	%	ASTM D3524	>5	12.9	11.3	11.7
Visc @ 100°C	cSt	ASTM D445	15.4	10.7	<u></u> 11.2	▲ 11.3

Customer Id: GFL891 Sample No.: GFL0093589 Lab Number: 06040319 Test Package: FLEET



To manage this report scan the QR code

To discuss the diagnosis or test data: Wes Davis +1 905-569-8600 x223 wesd@wearcheck.ca

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS Action Status Date Done By Description Resample -- -- ? We recommend an early resample to monitor this condition. Check Fuel/injector 2 We action that you should the final injection and the final injection are the final injection and the final injection and the final injection and the final injection and the final injection are the final injection and the final i

We advise that you check the fuel injection system.

HISTORICAL DIAGNOSIS

22 Nov 2023 Diag: Wes Davis

FUEL

System



We advise that you check the fuel injection system. We recommend that you drain the oil from the component if this has not already been done. We recommend an early resample to monitor this condition. Metal levels are typical for a new component breaking in. There is a high amount of fuel present in the oil. Tests confirm the presence of fuel in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The oil is no longer serviceable due to the presence of contaminants.



18 Apr 2023 Diag: Wes Davis

FUEL



We advise that you check the fuel injection system. We recommend that you drain the oil from the component if this has not already been done. We recommend an early resample to monitor this condition. All component wear rates are normal. There is a high amount of fuel present in the oil. Tests confirm the presence of fuel in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The oil is no longer serviceable due to the presence of contaminants.

view report

30 Mar 2023 Diag: Don Baldridge

FUEL



We advise that you check the fuel injection system. We recommend that you drain the oil and perform a filter service on this component if not already done. We recommend an early resample to monitor this condition. All component wear rates are normal. There is a high amount of fuel present in the oil. Fuel is present in the oil and is lowering the viscosity. The BN result indicates that there is suitable alkalinity remaining in the oil. The oil is no longer serviceable due to the presence of contaminants.





OIL ANALYSIS REPORT

Sample Rating Trend





427092-402367

Component

Diesel Engine

PETRO CANADA DURON SHP 15W40 (--- GAL)

DIAGNOSIS

Recommendation

We advise that you check the fuel injection system. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

Wear

All component wear rates are normal.

Contamination

There is a high amount of fuel present in the oil. Tests confirm the presence of fuel in the oil.

Fluid Condition

The BN result indicates that there is suitable alkalinity remaining in the oil. Fuel is present in the oil and is lowering the viscosity. The oil is no longer serviceable due to the presence of contaminants.

GAL)								
SAMPLE INFOR	RMATION	method	limit/base	current	history1	history2		
Sample Number		Client Info		GFL0093589	GFL0093600	GFL0078052		
Sample Date		Client Info		19 Dec 2023	22 Nov 2023	18 Apr 2023		
Machine Age	hrs	Client Info		17903	17732	451423		
Oil Age	hrs	Client Info		643	472	0		
Oil Changed		Client Info		Changed	Not Changd	Not Changd		
Sample Status				SEVERE	SEVERE	SEVERE		
CONTAMINA	ΓΙΟΝ	method	limit/base	current	history1	history2		
Water		WC Method	>0.2	NEG	NEG	NEG		
Glycol		WC Method		NEG	NEG	NEG		
WEAR METAI	_S	method	limit/base	current	history1	history2		
Iron	ppm	ASTM D5185m	>100	17	12	21		
Chromium	ppm	ASTM D5185m	>20	<1	<1	1		
Nickel	ppm	ASTM D5185m	>4	0	0	0		
Titanium	ppm	ASTM D5185m		<1	<1	0		
Silver	ppm	ASTM D5185m	>3	0	0	0		
Aluminum	ppm	ASTM D5185m	>20	1	1	3		
Lead	ppm	ASTM D5185m	>40	3	2	5		
Copper	ppm	ASTM D5185m	>330	<1	<1	<1		
Tin	ppm	ASTM D5185m	>15	0	0	<1		
Vanadium	ppm	ASTM D5185m		<1	<1	0		
Cadmium	ppm	ASTM D5185m		0	0	0		
ADDITIVES		method	limit/base	current	history1	history2		
Boron	ppm	ASTM D5185m	0	0	0	0		
Barium	ppm	ASTM D5185m	0	0	0	0		
Molybdenum	ppm	ASTM D5185m	60	51	53	55		
Manganese	ppm	ASTM D5185m	0	0	<1	<1		
Magnesium	ppm	ASTM D5185m	1010	770	879	849		
Calcium	ppm	ASTM D5185m	1070	847	930	991		
Phosphorus	ppm	ASTM D5185m	1150	799	850	922		
Zinc	ppm	ASTM D5185m	1270	971	1167	1170		
Sulfur	ppm	ASTM D5185m	2060	2287	2665	2808		
CONTAMINA	NTS	method	limit/base	current	history1	history2		
Silicon	ppm	ASTM D5185m	>25	3	2	4		
Sodium	ppm	ASTM D5185m		4	4	2		
Potassium	ppm	ASTM D5185m	>20	0	<1	2		
Fuel	%	ASTM D3524	>5	12.9	11.3	11.7		
	70	710 1111 00001		•	*			
INFRA-RED	76	method	limit/base	current	history1	history2		
INFRA-RED Soot %	%			current 0.5		history2		
		method	limit/base		history1	•		
Soot %	%	method *ASTM D7844	limit/base	0.5	history1	0.6		
Soot % Nitration	% Abs/cm Abs/.1mm	method *ASTM D7844 *ASTM D7624	limit/base >3 >20	0.5 11.5	history1 0.4 10.5	0.6 12.2		
Soot % Nitration Sulfation FLUID DEGRA	% Abs/cm Abs/.1mm DATION	method *ASTM D7844 *ASTM D7624 *ASTM D7415	limit/base >3 >20 >30	0.5 11.5 22.3 current	history1 0.4 10.5 21.2 history1	0.6 12.2 22.9 history2		
Soot % Nitration Sulfation	% Abs/cm Abs/.1mm	method *ASTM D7844 *ASTM D7624 *ASTM D7415 method	limit/base >3 >20 >30 limit/base >25	0.5 11.5 22.3	history1 0.4 10.5 21.2	0.6 12.2 22.9		




Base Number

10.0

Base Number (mg KOH/g)

0.0

OIL ANALYSIS REPORT




VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG


Abnormal			1111			Ш	11
16 - Base						A	
Abroma	$\overline{}$		1	\searrow	\checkmark	1	
10	\					1	
8	6	-	- 2		2		
Jan31/19 May21/19	17/1	Apr9/21	Feb 9/2;	Jun8/2.	ec13/2;	Feb2/2;	Apr18/2;








GRAPHS Ferrous Alloys















Laboratory Sample No. Lab Number

Unique Number : 10795548

: GFL0093589 : 06040319

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Recieved : 20 Dec 2023 Diagnosed

: 22 Dec 2023 Diagnostician : Wes Davis Test Package : FLEET (Additional Tests: PercentFuel)

Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

GFL Environmental - 891 - Oklahoma City Hauling

1001 South Rockwell Oklahoma City, OK US 73128

Contact: Andy Smith andrew.smith@gflenv.com T: (405)306-1651