

# **PROBLEM SUMMARY**

## Sample Rating Trend


**FUEL** 


729105 Component

**Diesel Engine** 

PETRO CANADA DURON SHP 15W40 (--- GAL)

### **COMPONENT CONDITION SUMMARY**





#### RECOMMENDATION

We advise that you check the fuel injection system. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS										
Sample Status				SEVERE	NORMAL	NORMAL				
Fuel	%	ASTM D3524	>5	9.2	<1.0	<1.0				
Viec @ 100°C	cSt	ASTM DAAS	15.4	A 10.8	1/15	1/1 1				

Customer Id: GFL408 Sample No.: GFL0086927 Lab Number: 06043865 Test Package: FLEET



To manage this report scan the QR code

To discuss the diagnosis or test data: Wes Davis +1 905-569-8600 x223 wesd@wearcheck.ca

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

# RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Resample			?	We recommend an early resample to monitor this condition.
Check Fuel/injector System			?	We advise that you check the fuel injection system.

#### HISTORICAL DIAGNOSIS

04 Dec 2023 Diag: Wes Davis

#### NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.



#### 07 Sep 2023 Diag: Wes Davis

#### NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

# view report

#### 29 Jun 2023 Diag: Wes Davis

#### NORMAL




Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.





# **OIL ANALYSIS REPORT**

Sample Rating Trend





729105 Component

**Diesel Engine** 

PETRO CANADA DURON SHP 15W40 (--- GAL)

# DIAGNOSIS

#### Recommendation

We advise that you check the fuel injection system. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

#### Wear

All component wear rates are normal.

#### Contamination

There is a high amount of fuel present in the oil. Tests confirm the presence of fuel in the oil.

#### ▲ Fluid Condition


The BN result indicates that there is suitable alkalinity remaining in the oil. Fuel is present in the oil and is lowering the viscosity. The oil is no longer serviceable due to the presence of contaminants.


GAL)		Jan2023	Apr2023 Jun2023	Jun 2023 Sep 2023 Dec 2023	Dec2023	
SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GFL0086927	GFL0086955	GFL0086934
Sample Date		Client Info		18 Dec 2023	04 Dec 2023	07 Sep 2023
Machine Age	hrs	Client Info		22822	22400	22113
Oil Age	hrs	Client Info		600	0	500
Oil Changed		Client Info		Changed	N/A	Not Changd
Sample Status				SEVERE	NORMAL	NORMAL
CONTAMINAT	ION	method	limit/base	current	history1	history2
Water		WC Method	>0.2	NEG	NEG	NEG
Glycol		WC Method		NEG	NEG	NEG
WEAR METAL	.S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>110	11	8	3
Chromium	ppm	ASTM D5185m	>4	<1	<1	0
Nickel	ppm	ASTM D5185m	>2	0	0	0
Titanium	ppm	ASTM D5185m		0	<1	0
Silver	ppm	ASTM D5185m	>2	0	0	0
Aluminum	ppm	ASTM D5185m	>25	<1	<1	<1
Lead	ppm	ASTM D5185m	>45	2	0	<1
Copper	ppm	ASTM D5185m	>85	2	<1	0
Tin	ppm	ASTM D5185m	>4	<1	0	<1
Vanadium	ppm	ASTM D5185m		0	<1	<1
Cadmium	ppm	ASTM D5185m		0	<1	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	5	4	5
Barium	ppm	ASTM D5185m	0	<1	0	0
Molybdenum	ppm	ASTM D5185m	60	53	57	60
Manganese	ppm	ASTM D5185m	0	<1	0	0
Magnesium	ppm	ASTM D5185m	1010	843	952	1016
Calcium	ppm	ASTM D5185m	1070	929	1024	1159
Phosphorus	ppm	ASTM D5185m	1150	978	1035	1046
Zinc	ppm	ASTM D5185m	1270	1126	1252	1272
Sulfur	ppm	ASTM D5185m	2060	2645	3024	3796
CONTAMINAN	ITS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>30	3	5	4
Sodium	ppm	ASTM D5185m		5	<1	<1
Potassium	ppm	ASTM D5185m	>20	0	0	0
Fuel	%	ASTM D3524	>5	9.2	<1.0	<1.0
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	0.5	0.4	0.1
Nitration	Abs/cm	*ASTM D7624	>20	8.3	4.6	4.6
Sulfation	Abs/.1mm	*ASTM D7415	>30	19.2	17.6	16.9
FLUID DEGRA	DATION	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	15.3	12.5	12.5
Base Number (BN)	mg KOH/g	ASTM D2896	9.8	7.3	9.2	9.3
- ( -)	0					



# **OIL ANALYSIS REPORT**









Certificate L2367

Laboratory Sample No. Lab Number **Unique Number** 

: GFL0086927

: 06043865 : 10804473

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Recieved : 22 Dec 2023 : 27 Dec 2023 Diagnosed Diagnostician : Wes Davis

Test Package : FLEET ( Additional Tests: FuelDilution, PercentFuel ) To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

GFL Environmental - 408 - Brown City

4235 M-53 BROWN CITY, MI US 48416

NONE

NONE

NONE

NONE

NONE

NONE

**NORML** 

NORML

NEG

NEG

14.1

Contact: WILLIAM DEOLA bdeola@gflenv.com

T: (810)238-2836

F: