


# **OIL ANALYSIS REPORT**

Sample Rating Trend



NORMAL



Machine Id **638628** 

Component
Diesel Engine

PETRO CANADA DURON SHP 10W30 (--- GAL)

## DIAGNOSIS

### Recommendation

Resample at the next service interval to monitor. Please specify the component make and model with your next sample.

#### Wear

Metal levels are typical for a new component breaking in.

## Contamination

Elevated aluminum (Al) and/or lead (Pb) and potassium (K) levels in your metals analysis are likely a result of solder flux release into the lubricant and is common on new equipment/components. There is no indication of any contamination in the oil.

## **Fluid Condition**

The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

GAL)			Feb2023	0ct2023		
SAMPLE INFOR	RMATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0097372	PCA0083855	
Sample Date		Client Info		23 Oct 2023	08 Feb 2023	
Machine Age	mls	Client Info		60854	52437	
Oil Age	mls	Client Info		8417	52437	
Oil Changed		Client Info		Changed	Changed	
Sample Status				NORMAL	NORMAL	
CONTAMINA	TION	method	limit/base	current	history1	history2
Fuel		WC Method	>5	<1.0	<1.0	
Water		WC Method	>0.2	NEG	NEG	
Glycol		WC Method		NEG	NEG	
WEAR META	LS	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>100	32	71	
Chromium	ppm	ASTM D5185m	>20	2	5	
Nickel	ppm	ASTM D5185m	>4	0	<1	
Titanium	ppm	ASTM D5185m		14	<1	
Silver	ppm	ASTM D5185m	>3	<1	0	
Aluminum	ppm	ASTM D5185m	>20	18	70	
Lead	ppm	ASTM D5185m	>40	0	0	
Copper	ppm	ASTM D5185m	>330	63	194	
Tin	ppm	ASTM D5185m	>15	2	4	
Vanadium	ppm	ASTM D5185m		<1	0	
Cadmium	ppm	ASTM D5185m		0	0	
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	2	20	24	
Barium	ppm	ASTM D5185m	0	0	0	
Molybdenum	ppm	ASTM D5185m	50	49	47	
Manganese	ppm	ASTM D5185m	0	2	6	
Magnesium	ppm	ASTM D5185m	950	798	546	
Calcium	ppm	ASTM D5185m	1050	1341	1685	
Phosphorus	ppm	ASTM D5185m	995	923	749	
Zinc	ppm	ASTM D5185m	1180	1238	952	
Sulfur	ppm	ASTM D5185m	2600	2969	1999	
CONTAMINA	NTS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	6	10	
Sodium	ppm	ASTM D5185m		3	7	
Potassium	ppm	ASTM D5185m	>20	44	174	
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	0.5	1.1	
Nitration	Abs/cm	*ASTM D7624	>20	8.0	12.0	
Sulfation	Abs/.1mm	*ASTM D7415	>30	19.7	24.6	
FLUID DEGRA	DATION	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	16.1	24.8	
Base Number (BN)		ASTM D2896	-	8.2	6.8	
(	3 3					

Contact/Location: RON ROBERTS - MILLAN



## **OIL ANALYSIS REPORT**







Laboratory Sample No. Lab Number **Unique Number** 

: PCA0097372 : 06048231 : 10808839 Test Package : MOB 1 ( Additional Tests: TBN )

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : 29 Dec 2023 Recieved Diagnosed

: 02 Jan 2024 Diagnostician : Wes Davis

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

**MILLER TRUCK LEASING #123** 

**66 KELLER AVENUE** LANCASTER, PA US 17601

Contact: RON ROBERTS rroberts@millertransgroup.com

Contact/Location: RON ROBERTS - MILLAN

T: (717)945-6205 F: (717)945-5818