

## RECOMMENDATION

We advise that you check the fuel injection system. Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS								
Sample Status				SEVERE	ABNORMAL	NORMAL		
Fuel	%	ASTM D3524	>5	🛑 16.8	<1.0	<1.0		
Visc @ 100°C	cSt	ASTM D445	15.4	<b>10.1</b>	14.2	14.1		

Customer Id: GFL856 Sample No.: GFL0092122 Lab Number: 06084275 Test Package: FLEET



To manage this report scan the QR code

*To discuss the diagnosis or test data:* Jonathan Hester +1 919-379-4092 x4092 jhester@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDE	D ACTIONS			
Action	Status	Date	Done By	Description
Change Fluid			?	Oil and filter change at the time of sampling has been noted.
Change Filter			?	Oil and filter change at the time of sampling has been noted.
Resample			?	We recommend an early resample to monitor this condition.
Check Fuel/injector System			?	We advise that you check the fuel injection system.

# HISTORICAL DIAGNOSIS



# 02 Dec 2023 Diag: Jonathan Hester

07 Jun 2023 Diag: Jonathan Hester

We recommend you service the filters on this component. Resample at the next service interval to monitor.All component wear rates are normal. There is an abnormal amount of solids and carbon present in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.



view report

#### NORMAL



Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

### 14 Mar 2023 Diag: Jonathan Hester



We advise that you check for the source of the coolant leak. Check for low coolant level. We recommend that you drain the oil and perform a filter service on this component if not already done. We recommend an early resample to monitor this condition.All component wear rates are normal. Sodium and/or potassium levels are high. Test for glycol is positive. The BN result indicates that there is suitable alkalinity remaining in the oil. The oil is no longer serviceable due to the presence of contaminants.





# **OIL ANALYSIS REPORT**

Sample Rating Trend





Machine Id 723022-361626 Component

Diesel Engine

PETRO CANADA DURON SHP 15W40 (--- GAL)

SAMPLE INFOR	<u>RMATION</u>	method	limit/base	current	history1	history2
Sample Number		Client Info		GFL0092122	GFL0092088	GFL008467
Sample Date		Client Info		06 Feb 2024	02 Dec 2023	07 Jun 2023
Machine Age	hrs	Client Info		18953	233406	233406
Oil Age	hrs	Client Info		600	228171	0
Oil Changed		Client Info		Changed	Not Changd	Not Changd
Sample Status				SEVERE	ABNORMAL	NORMAL
CONTAMINA	ΓΙΟΝ	method	limit/base	current	history1	history2
Water		WC Method	>0.2	NEG	NEG	NEG
Glycol		WC Method		NEG	NEG	NEG
WEAR METAI	_S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>80	84	66	33
Chromium	ppm	ASTM D5185m	>5	3	3	1
Nickel	ppm	ASTM D5185m	>2	<1	0	<1
Titanium	ppm	ASTM D5185m		<1	0	0
Silver	ppm	ASTM D5185m	>3	0	0	0
Aluminum	ppm	ASTM D5185m	>30	7	5	4
Lead	ppm	ASTM D5185m	>30	3	2	0
Copper	ppm	ASTM D5185m	>150	5	7	2
Tin	ppm	ASTM D5185m	>5	2	<1	<1
Vanadium	ppm	ASTM D5185m		<1	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	10	1	4
Barium	ppm	ASTM D5185m	0	0	2	0
Molybdenum	ppm	ASTM D5185m	60	45	56	59
Manganese	ppm	ASTM D5185m	0	<1	0	<1
Magnesium	ppm	ASTM D5185m	1010	637	826	954
Calcium	ppm	ASTM D5185m	1070	995	1014	1114
Phosphorus	ppm	ASTM D5185m	1150	727	871	1014
Zinc	ppm	ASTM D5185m	1270	911	1090	1238
Sulfur	ppm	ASTM D5185m	2060	1980	2589	3437
CONTAMINA	NTS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>20	14	13	9
Sodium	ppm	ASTM D5185m		11	11	59
Potassium	ppm	ASTM D5185m	>20	0	4	4
Fuel	%	ASTM D3524	>5	<b>e</b> 16.8	<1.0	<1.0
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	1.5	<b>4</b> .2	2.4
Nitration	Abs/cm	*ASTM D7624	>20	16.0	16.1	12.4
Sulfation	Abs/.1mm	*ASTM D7415	>30	27.6	30.0	25.1
FLUID DEGRA	DATION	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	33.1	23.7	21.6

# Recommendation

We advise that you check the fuel injection system. Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

# Wear

All component wear rates are normal.

## Contamination


There is a high amount of fuel present in the oil.


### Fluid Condition


Fuel is present in the oil and is lowering the viscosity. The BN result indicates that there is suitable alkalinity remaining in the oil. The oil is no longer serviceable due to the presence of contaminants.



# **OIL ANALYSIS REPORT**








VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
FLUID PROPE	RTIES	method	limit/base	current	history1	history2
Visc @ 100°C	cSt	ASTM D445	15.4	<b>1</b> 0.1	14.2	14.1
GRAPHS						

Ferrous Alloys



Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Certificate L2367

F: