


OIL ANALYSIS REPORT

Sam



VISCOSITY



714044

Component **Diesel Engine**

PETRO CANADA DURON SHP 15W40 (--- GAL)

DIAGNOSIS

▲ Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor.

Wear

Metal levels are typical for a new component breaking in.

Contamination

Fuel content negligible. There is no indication of any contamination in the oil.


▲ Fluid Condition

The oil viscosity is lower than normal. The BN result indicates that there is suitable alkalinity remaining in the oil. Confirm oil type.

history2
history2
history2
history2
 history2
history2
history2
history2
history2 history2 history2 history2



OIL ANALYSIS REPORT







Laboratory Sample No.

: GFL0110137 Lab Number : 06085774

Unique Number : 10873219

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 12 Feb 2024 **Tested**

Diagnosed **Test Package**: FLEET (Additional Tests: FuelDilution, PercentFuel)

: 14 Feb 2024 : 14 Feb 2024 - Jonathan Hester

GFL Environmental - 916 - Greenbay HC 1799 County Trunk PP DePere, WI US 54115

Contact: Travis Runge travis.runge@gflenv.com T: (920)351-2341

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)