

COOLANT REPORT

Sample Rating Trend

FUEL



Machine Id
326725
 Component
Diesel Exhaust Fluid (DEF)
 Fluid
DEF (Diesel Exhaust Fluid) (--- QTS)



DIAGNOSIS

▲ Recommendation

We advise that you check for the source of gasoline. Recommend drain diesel exhaust fluid (def) if not already done and flush before refilling with diesel exhaust fluid (def). Please note that the diesel exhaust fluid (def) was too contaminated to perform the normal laboratory tests.

▲ Contamination

Sample consists entirely of gasoline.



Fluid Condition

The diesel exhaust fluid (def) is no longer serviceable due to the presence of contaminants.


SAMPLE INFORMATION

	method	limit/base	current	history1	history2
Sample Number	Client Info		PCA0114578	---	---
Sample Date	Client Info		12 Feb 2024	---	---
Machine Age	mls	Client Info	0	---	---
Oil Age	mls	Client Info	0	---	---
Oil Changed		Client Info	N/A	---	---
Sample Status			SEVERE	---	---


VISUAL

	method	limit/base	current	history1	history2
Color				no image	no image
Bottom				no image	no image

COOLANT REPORT



GRAPHS



Certificate L2367

Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : PCA0114578
Lab Number : 06095965
Unique Number : 10888818
Test Package : MOB 1 (Additional Tests: PERCENTFUEL)

Received : 21 Feb 2024
Tested : 01 Mar 2024
Diagnosed : 01 Mar 2024 - Doug Bogart

MILLER TRUCK LEASING #118
 2196 BENNETT ROAD
 PHILADELPHIA, PA
 US 19116

Contact: ROSTY VITER
 rviter@millertransgroup.com

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T: (215)552-9832
 F: (215)552-9892