


PROBLEM SUMMARY




(83J 44U) 913147

Component **Diesel Engine**

PETRO CANADA DURON SHP 15W40 (--- GAL)



COMPONENT CONDITION SUMMARY



RECOMMENDATION

No corrective action is recommended at this time. Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS							
Sample Status				SEVERE	ABNORMAL	NORMAL	
Nickel	ppm	ASTM D5185m	>5	▲ 11	▲ 12	7	

Customer Id: GFL836 Sample No.: GFL0114125 Lab Number: 06114974 Test Package: FLEET

To manage this report scan the QR code

To discuss the diagnosis or test data: Jonathan Hester +1 919-379-4092 x4092 ihester@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS Action Status Date Done By Description Change Fluid -- -- ? Oil and filter change at the time of sampling has been noted. Change Filter -- -- ? Oil and filter change at the time of sampling has been noted.

HISTORICAL DIAGNOSIS

22 Feb 2024 Diag: Jonathan Hester

WEAR



No corrective action is recommended at this time. Resample at the next service interval to monitor. Valve wear is indicated. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.



22 Jan 2024 Diag: Don Baldridge

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.



04 Jan 2024 Diag: Wes Davis

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.






OIL ANALYSIS REPORT



(83J 44U) 913147 Component

Diesel Engine

PETRO CANADA DURON SHP 15W40 (--- GAL)





DIAGNOSIS

▲ Recommendation

No corrective action is recommended at this time. Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

▲ Wear

Valve wear is indicated.

Contamination

There is no indication of any contamination in the


Fluid Condition


The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.


N SHP 15W40 (GAL)	Feb2023 Au	g2023 Oct2023 Oct2023	Dec2023 Jan2024 Jan2024 Feb20	24 Mar2024	
SAMPLE INFOR	RMATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GFL0114125	GFL0108060	GFL0108129
Sample Date		Client Info		05 Mar 2024	22 Feb 2024	22 Jan 2024
Machine Age	hrs	Client Info		2970	2908	2780
Oil Age	hrs	Client Info		1857	1051	0
Oil Changed		Client Info		Changed	Not Changd	Not Changd
Sample Status				SEVERE	ABNORMAL	NORMAL
CONTAMINA	ΓΙΟΝ	method	limit/base	current	history1	history2
Fuel		WC Method	>3.0	<1.0	<1.0	<1.0
Water		WC Method	>0.2	NEG	NEG	NEG
Glycol		WC Method		NEG	NEG	NEG
WEAR META	LS	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>120	15	13	9
Chromium	ppm	ASTM D5185m	>20	<1	<1	<1
Nickel	ppm	ASTM D5185m	>5	▲ 11	1 2	7
Titanium	ppm	ASTM D5185m	>2	0	0	0
Silver	ppm	ASTM D5185m	>2	0	0	0
Aluminum	ppm	ASTM D5185m	>20	<1	2	1
Lead	ppm	ASTM D5185m	>40	<1	0	0
Copper	ppm	ASTM D5185m	>330	5	6	4
Tin	ppm	ASTM D5185m	>15	0	1	1
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	15	23	23
Barium	ppm	ASTM D5185m	0	0	0	0
Molybdenum	ppm	ASTM D5185m	60	58	64	56
Manganese	ppm	ASTM D5185m	0	<1	<1	<1
Magnesium	ppm	ASTM D5185m	1010	1130	1136	996
Calcium	ppm	ASTM D5185m	1070	913	932	821
Phosphorus	ppm	ASTM D5185m	1150	1032	1135	1002
Zinc	ppm	ASTM D5185m	1270	1296	1360	1153
Sulfur	ppm	ASTM D5185m	2060	3674	3346	3001
CONTAMINA	NTS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	6	8	8
Sodium	ppm	ASTM D5185m		7	8	7
Potassium	ppm	ASTM D5185m	>20	2	3	2
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>4	0.4	0.4	0.3
Nitration	Abs/cm	*ASTM D7624	>20	10.1	9.6	8.8
Sulfation	Abs/.1mm	*ASTM D7415	>30	20.7	20.4	19.8
FLUID DEGRA	DATION	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	. 05	40.0	100	17.2
Oxidation	AUS/.1111111	A311VI D7414	>25	18.8	18.0	17.2



OIL ANALYSIS REPORT









VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG


FLUID PROPI	ERHES	method	limit/base	current	history1	history2
Visc @ 100°C	cSt	ASTM D445	15.4	12.2	12.0	12.1


GRAPHS















Certificate L2367

Laboratory Sample No. Lab Number : 06114974

Test Package : FLEET

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : GFL0114125

Unique Number: 10923807

Received **Tested** Diagnosed

: 11 Mar 2024 : 12 Mar 2024 : 13 Mar 2024 - Jonathan Hester

GFL Environmental - 836 - Kansas City Hauling

7801 East Truman Road Kansas City, MO US 64126

Contact: Loyce Stewart loyce.stewart@gflenv.com

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T:

F: