

# **OIL ANALYSIS REPORT**

Iron

Tin

# G.LOPES CONSTRUCTION INC./ON-ROAD **PU248**

Component **Diesel Engine** 

PETRO CANADA DURON SHP 15W40 (--- GAL)

## DIAGNOSIS

### Recommendation

We recommend that you drain the oil from the component if this has not already been done. We recommend an early resample to monitor this condition. Please specify the component make and model with your next sample.

#### Wear

All component wear rates are normal.

### Contamination

There is a moderate amount of fuel present in the oil. Tests confirm the presence of fuel in the oil.

#### Fluid Condition

The BN result indicates that there is suitable alkalinity remaining in the oil. Fuel is present in the oil and is lowering the viscosity. The oil is no longer serviceable due to the presence of contaminants.



9.8

7.81

5.97



# **OIL ANALYSIS REPORT**





Certificate L2367

18

10

8

Laboratory

Sample No.

Lab Number