


PROBLEM SUMMARY


Machine Id **927071-223253**

Component **Hydraulic System**

AW HYDRAULIC OIL ISO 46 (--- GAL)



COMPONENT CONDITION SUMMARY



RECOMMENDATION

Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation. Please specify the brand, type, and viscosity of the oil on your next sample.

PROBLEMATIC TEST RESULTS									
Sample Status			SEVERE	SEVERE					
Particles >4µm	ASTM D7647	>5000	264908	1 60639					
Particles >6μm	ASTM D7647	>1300	18435	2 1461					
Oil Cleanliness	ISO 4406 (c)	>19/17/14	25/21/13	25/22/15					

Customer Id: GFL823 Sample No.: GFL0065704 Lab Number: 06131957 Test Package: FLEET

To manage this report scan the QR code

To discuss the diagnosis or test data: Wes Davis +1 905-569-8600 x223 wesd@wearcheck.ca

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS							
Action	Status	Date	Done By	Description			
Change Filter			?	We recommend you service the filters on this component.			
Resample			?	Resample in 30-45 days to monitor this situation.			
Information Required			?	Please specify the brand, type, and viscosity of the oil on your next sample.			
Check Breathers			?	The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather.			
Check Seals			?	Check seals and/or filters for points of contaminant entry.			


HISTORICAL DIAGNOSIS

19 Dec 2023 Diag: Wes Davis

ISO



Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) AW HYDRAULIC OIL ISO 46. Please confirm.







OIL ANALYSIS REPORT

927071-223253

Component

Hydraulic System

AW HYDRAULIC OIL ISO 46 (--- GAL)

Sample Rating Trend

DIAGNOSIS

Recommendation

Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation. Please specify the brand, type, and viscosity of the oil on your next sample.

Wear

All component wear rates are normal.

▲ Contamination

There is a high amount of silt (particulates < 14 microns in size) present in the oil.


Fluid Condition

The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

			Dec2023	Mar2024		
SAMPLE INFORI	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GFL0065704	GFL0065693	
Sample Date		Client Info		20 Mar 2024	19 Dec 2023	
Machine Age	mls	Client Info		0	0	
Oil Age	mls	Client Info		0	0	
Oil Changed		Client Info		Not Changd	N/A	
Sample Status				SEVERE	SEVERE	
CONTAMINAT	ION	method	limit/base	current	history1	history2
Water		WC Method	>0.1	NEG	NEG	
WEAR METAL	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	9	10	
Chromium	ppm	ASTM D5185m	>10	3	3	
Nickel	ppm	ASTM D5185m	>10	1	0	
Titanium	ppm	ASTM D5185m		<1	<1	
Silver	ppm	ASTM D5185m		0	0	
Aluminum	ppm	ASTM D5185m	>10	2	2	
Lead	ppm	ASTM D5185m	>10	0	0	
Copper	ppm	ASTM D5185m	>75	1	1	
Tin	ppm	ASTM D5185m	>10	<1	0	
Vanadium	ppm	ASTM D5185m		0	0	
Cadmium	ppm	ASTM D5185m		0	0	
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	5	0	0	
Barium	ppm	ASTM D5185m	5	0	0	
Molybdenum	ppm	ASTM D5185m	5	2	2	
Manganese	ppm	ASTM D5185m		<1	0	
Magnesium	ppm	ASTM D5185m	25	21	22	
Calcium	ppm	ASTM D5185m	200	117	105	
Phosphorus	ppm	ASTM D5185m	300	292	367	
Zinc	ppm	ASTM D5185m	370	443	443	
Sulfur	ppm	ASTM D5185m	2500	1055	981	
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>20	3	2	
Sodium	ppm	ASTM D5185m		6	3	
Potassium	ppm	ASTM D5185m	>20	3	3	
FLUID CLEANI	INESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>5000	264908	1 60639	
Particles >6µm		ASTM D7647	>1300	18435	1 21461	
Particles >14μm		ASTM D7647	>160	69	166	
Particles >21µm		ASTM D7647	>40	16	26	
Particles >38μm		ASTM D7647	>10	0	0	
Particles >71μm		ASTM D7647	>3	0	0	
Oil Cleanliness		ISO 4406 (c)	>19/17/14	25/21/13	2 5/22/15	
FLUID DEGRA	DATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045	0.57	0.44	0.39	



OIL ANALYSIS REPORT







Laboratory Sample No.

: GFL0065704 Lab Number : 06131957 Unique Number: 10951422

Tested Diagnosed

Test Package: FLEET (Additional Tests: PrtCount) To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Received

: 28 Mar 2024

: 29 Mar 2024

: 29 Mar 2024 - Wes Davis

GFL Environmental - 823 - Central Missouri Hauling

24461 Oak Grove Lane Sedalia, MO

US 65301 Contact: Terry Randolph

trandolph@gflenv.com

T: (660)631-2116