


PROBLEM SUMMARY


Machine Id


427023-442

Diesel Engine Fluid PETRO CANADA DURON SHP 15W40 (--- LTR)

COMPONENT CONDITION SUMMARY







RECOMMENDATION

We advise that you check the fuel injection system. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS							
Sample Status				SEVERE	SEVERE	SEVERE	
Fuel	%	ASTM D3524	>3.0	A 30.5	4 0.1	▲ 33.1	
Visc @ 100°C	cSt	ASTM D445	15.4	6 .9	▲ 5.5	6 .7	

Customer Id: GFL650 Sample No.: GFL0077794 Lab Number: 06135485 Test Package: FLEET



To manage this report scan the QR code

To discuss the diagnosis or test data: Wes Davis +1 905-569-8600 x223 wesd@wearcheck.ca

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDE	D ACTIONS			
Action Resample	Status	Date	Done By ?	Description We recomme
Check Fuel/injector System			?	We advise th

nend an early resample to monitor this condition.

hat you check the fuel injection system.

HISTORICAL DIAGNOSIS



04 Jan 2024 Diag: Wes Davis

We advise that you check the fuel injection system. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition. All component wear rates are normal. There is a high amount of fuel present in the oil. Tests confirm the presence of fuel in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. Fuel is present in the oil and is lowering the viscosity. The oil is no longer serviceable due to the presence of contaminants.







We advise that you check the fuel injection system. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition.All component wear rates are normal. There is a high amount of fuel present in the oil. Tests confirm the presence of fuel in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. Fuel is present in the oil and is lowering the viscosity. The oil is no longer serviceable due to the presence of contaminants.





11 Jul 2023 Diag: Wes Davis

We advise that you check the fuel injection system. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition.All component wear rates are normal. There is a high amount of fuel present in the oil. Tests confirm the presence of fuel in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. Fuel is present in the oil and is lowering the viscosity. The oil is no longer serviceable due to the presence of contaminants.







OIL ANALYSIS REPORT

Sample Rating Trend

FUEL

X

Machine Id 427023-442

Diesel Engine Fluid PETRO CANADA DURON SHP 15W40 (--- LTR)

DIAGNOSIS

Recommendation

We advise that you check the fuel injection system. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

Wear

All component wear rates are normal.

Contamination

There is a high amount of fuel present in the oil. Tests confirm the presence of fuel in the oil.


Fluid Condition


The BN result indicates that there is suitable alkalinity remaining in the oil. Fuel is present in the oil and is lowering the viscosity. The oil is no longer serviceable due to the presence of contaminants.

.TR)		Jct2020 Feb	2021 Apr2021 Nov2021	Jun2022 Jan2023 Jul2023	Jan2024	
SAMPLE INFOR	RMATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GFL0077794	GFL0077769	GFL0077805
Sample Date		Client Info		25 Mar 2024	04 Jan 2024	24 Oct 2023
Machine Age	hrs	Client Info		38070	515487	507407
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		Changed	Changed	Changed
Sample Status				SEVERE	SEVERE	SEVERE
CONTAMINA	TION	method	limit/base	current	history1	history2
Water		WC Method	>0.2	NEG	NEG	NEG
Glycol		WC Method		NEG	NEG	NEG
WEAR META	LS	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>120	4	8	5
Chromium	ppm	ASTM D5185m	>20	0	<1	0
Nickel	ppm	ASTM D5185m	>5	0	<1	0
Titanium	ppm	ASTM D5185m	>2	0	0	0
Silver	ppm	ASTM D5185m	>2	0	0	0
Aluminum	ppm	ASTM D5185m	>20	<1	2	1
Lead	ppm	ASTM D5185m	>40	0	<1	<1
Copper	ppm	ASTM D5185m	>330	3	10	4
Tin	ppm	ASTM D5185m	>15	0	1	<1
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	7	4	4
Barium	ppm	ASTM D5185m	0	0	0	0
Molybdenum	ppm	ASTM D5185m	60	42	36	39
Manganese	ppm	ASTM D5185m	0	0	<1	<1
Magnesium	ppm	ASTM D5185m	1010	683	590	654
Calcium	ppm	ASTM D5185m	1070	773	657	704
Phosphorus	ppm	ASTM D5185m	1150	768	662	738
Zinc	ppm	ASTM D5185m	1270	856	781	873
Sulfur	ppm	ASTM D5185m	2060	2560	1930	2063
CONTAMINA	NTS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	3	5	5
Sodium	ppm	ASTM D5185m		<1	2	<1
Potassium	ppm	ASTM D5185m	>20	0	0	<1
Fuel	%	ASTM D3524	>3.0	A 30.5	4 0.1	▲ 33.1
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>4	0.3	0.5	0.4
Nitration	Abs/cm	*ASTM D7624	>20	7.9	8.9	8.1
Sulfation	Abs/.1mm	*ASTM D7415	>30	16.2	17.0	16.5
FLUID DEGRA	DATION	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	12.7	13.4	12.6
Base Number (BN)	mg KOH/g	ASTM D2896	9.8	7.5	5.2	6.0




OIL ANALYSIS REPORT












VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
FLUID PROPE	RTIES	method	limit/base	current	history1	history2
Visc @ 100°C	cSt	ASTM D445	15.4	6 .9	▲ 5.5	6 .7
GRAPHS						

Ferrous Alloys







Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513 GFL Environmental - 650 - West Point Hauling Sample No. : GFL0077794 Received :01 Apr 2024 7825 Parham Landing Road Lab Number : 06135485 Tested : 04 Apr 2024 West Point, VA Unique Number : 10954950 Diagnosed : 04 Apr 2024 - Wes Davis US 23181 Test Package : FLEET (Additional Tests: PercentFuel) Contact: Jason Smith Certificate 12367 To discuss this sample report, contact Customer Service at 1-800-237-1369. jasonsmith@gflenv.com * - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F:

nv8/71

Feb16/21

nr79/71

Jul11/23

Jan 19/23

lan4/24

Report Id: GFL650 [WUSCAR] 06135485 (Generated: 04/05/2024 01:37:19) Rev: 1

Contact/Location: Jason Smith - GFL650

Page 4 of 4