

CONSTRUCTION EQUIPMENT

310188 VOLVO EC220E 310188 - FRONT RIGHT FINAL DRIVE



Oil Type: VOLVO PREMIUM GEAR OIL 80W-90 GL-5

Job No: 310188

| VOLVO | INCODMATIO | V | | |
|----------------|------------|--------------|---|------|
| | INFORMATIO | <u> </u> | _ | |
| Sample Number | | VCP260289 | | |
| Sample Date | | 30 Mar 2020 | | |
| Machine Hours | | 4011 | | |
| Oil Hours | | 0 | | |
| Oil Changed | | Changed | | |
| Sample Status | | ABNORMAL | | |
| | | | | |
| OIL CON | DITION | | | |
| | | | | |
| Visc @ 40°C | cSt | △ 305 | | |
| VOLVO | | | | |
| CONTAM | IINATION | | | |
| Silicon | | <u>▲</u> 641 | | |
| | ppm | | | |
| Sodium | ppm | 19 | | |
| Potassium | ppm | ■32 | | |
| VOLVO | | | | |
| WEAR M | IETALS | | | |
| PQ | | 185 | | |
| Iron | ppm | ■ 1553 | | |
| Copper | ppm | 4 | | |
| Lead | ppm | 2 | | |
| Tin | | 0 | | |
| Aluminum | ppm | <u> </u> | | |
| Chromium | ppm | ■28 | | |
| Molybdenum | ppm | 3 | | |
| Nickel | ppm | 2 | | |
| | ppm | 8 | | |
| Titanium | ppm | <1 | | |
| Silver | ppm | 28 | | |
| Manganese | ppm | | | |
| Vanadium | ppm | <1 | | |
| VOLVO | | | | |
| ADDITIV | ES | | | |
| Calcium | ppm | 333 | | |
| Magnesium | ppm | ■64 | | |
| Zinc | ppm | 47 | | |
| Phosphorus | ppm | ■ 1048 | | |
| Barium | ppm | ■ <1 | | |
| Boron | | 148 | | |
| DOTOTI | ppm | 140 | | |



STRONGCO EQUIPMENT--CALGARY

7923 54TH STREET SE CALGARY, AB CA T2C 4R7 Contact: Tracey Lewin tlewin@strongco.com T: (403)216-1010 F: (403)216-1016

Diagnosis

We advise that you check all areas where dirt can enter the system. The oil change at the time of sampling has been noted. Confirm the source of the lubricant being utilized for topup/fill. We recommend an early resample to monitor this condition. Aluminum ppm levels are noted. All other component wear rates are normal. Elemental levels of silicon (Si) and aluminum (Al) indicate alumina-silicate (coarse dirt) ingress. Viscosity of sample indicates oil is within SAE 80W140 range, advise investigate. This plus the additive levels indicates that this is not the same brand, or type of oil as reported. The oil is no longer serviceable due to the presence of contaminants.

Depot:VOLVO3909Unique No:5031159Signed:Kevin MarsonReport Date:08 Apr 2020



CONSTRUCTION EQUIPMENT





