

## **CONSTRUCTION EQUIPMENT**

305087 VOLVO EC380E 311590 - REAR LEFT FINAL DRIVE

Sample No: VCP273123

Oil Type: VOLVO PREMIUM GEAR OIL 80W-90 GL-5

**Job No:** 305087

VOLVO					
SAMPLE	<b>INFORMATION</b>				
Sample Number	<u>-</u>	VCP273123			
Sample Date		12 Nov 2021			
Machine Hours		3312			
Oil Hours		303			
Oil Changed		Not Changd			
Sample Status		NORMAL			
VOLVO	DITION				
OIL CONDITION					
Visc @ 40°C	cSt	<b>124</b>			
COLVO	MINATION				
	<u> </u>			<u> </u>	
Silicon	ppm	<b>101</b>			
Sodium	ppm	<b>3</b>			
Potassium	ppm	■ 5			
VOLVO					
WEAR N	METALS				
Iron	ppm	<b>462</b>			
Copper	ppm	<u> </u>			
Lead	ppm	<b>0</b>			
Tin	ppm	■0			
Aluminum	ppm	<b>■20</b>			
Chromium	ppm	<b>■</b> 7			
Molybdenum	ppm	<b>■&lt;1</b>			
Nickel	ppm	<1			
Titanium	ppm	1			
Silver	ppm	0			
Manganese	ppm	<b>4</b>			
Vanadium	ppm	<1			
ADDITIV	IEC				
Calcium	ppm	■26			
Magnesium	ppm	<b>6</b>			
Zinc	ppm	11			
Phosphorus	ppm	1934			
Barium	ppm	■ 0			
Boron	ppm	<b>109</b>			



#### STRONGCO EQUIPMENT-EDMONTON

25616 117 Ave NW Acheson, AB CA T7X 6C2 Contact: Jonathan Morton jmorton@strongco.com T: (780)464-1909 F: (780)464-0434

### Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO3908Unique No:5331681Signed:Kevin MarsonReport Date:24 Dec 2021



# **CONSTRUCTION EQUIPMENT**





