

 Sample No:
 VCP349546

 Oil Type:
 SAE 0W40

 Job No:
 314854



STRONGCO EQUIPMENT-EDMONTON

25616 117 Ave NW Acheson, AB CA T7X 6C2 Contact: Jonathan Morton jmorton@strongco.com T: (780)464-1909 F: (780)464-0434

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid.

Viscosity of sample indicates oil is within SAE 20 range, advise investigate. The condition of the fluid is acceptable for the time in service.

Depot:VOLVO3908Unique No:5410087Signed:Kevin MarsonReport Date:08 Jun 2022



CONSTRUCTION EQUIPMENT





GRAPHS

