



CONSTRUCTION EQUIPMENT

329492 VOLVO EC350EL 314444 - SWING DRIVE



Sample No: VCP347010
Oil Type: VOLVO API GL-5 SAE 75W90
Job No: 329492



SAMPLE INFORMATION

Sample Number	VCP347010	---	---	---
Sample Date	23 Jun 2022	---	---	---
Machine Hours	8	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

STRONGCO EQUIPMENT INC (STE- FOY)

175, rue de Rotterdam
 St-Augustin-de-Desmaures, QC
 CA G3A 2K2
 Contact: Michel Lepage
 mlepage@strongco.com
 T: (418)870-1700
 F: (418)870-1701



OIL CONDITION

Visc @ 40°C	cSt	173	---	---	---
-------------	-----	-----	-----	-----	-----



CONTAMINATION

Silicon	ppm	█ 1	---	---	---
Sodium	ppm	█ <1	---	---	---
Potassium	ppm	█ <1	---	---	---



WEAR METALS

Iron	ppm	█ 2	---	---	---
Copper	ppm	█ 0	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	0	---	---	---
Aluminum	ppm	0	---	---	---
Chromium	ppm	0	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 0	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	█ 3	---	---	---
Magnesium	ppm	█ <1	---	---	---
Zinc	ppm	█ 7	---	---	---
Phosphorus	ppm	318	---	---	---
Barium	ppm	█ 4	---	---	---
Boron	ppm	<1	---	---	---

Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill. Échantillonner de nouveau l'équipement au prochain intervalle de vidange afin d'en surveiller la condition. Les taux d'usure de tous les composants sont normaux. Il n'y a aucun indice de contamination dans l'huile. La viscosité de l'échantillon se situe dans la portée de l'ISO 150; nous vous conseillons de vérifier. Ceci, en plus des niveaux d'additifs, indique que la marque ou le type d'huile ne correspond pas à ce qui a été signalé. L'état de l'huile est acceptable pour la durée de service.

Depot: VOLVO0228
Unique No: 5421975
Signed: Kevin Marson
Report Date: 27 Jun 2022



CONSTRUCTION EQUIPMENT



GRAPHS

