

CONSTRUCTION EQUIPMENT 8-374171 2547 - FRONT AXLE



Sample No: VCP380470
Oil Type: NOT GIVEN
Job No: 8-374171

SAMPLE	INFORMATIO	N		
Sample Number		VCP380470	 	
Sample Date		11 Aug 2023	 	
Machine Hours		9606	 	
Oil Hours		0	 	
Oil Changed		N/A	 	
Sample Status		NORMAL	 	
OIL CONE	DITION			
Visc @ 40°C	cSt	■39.0	 	
VOLVO				
CONTAM	INATION			
Silicon	ppm	■8	 	
Sodium	ppm	■ 9	 	
Potassium	ppm	2	 	
WEAR M	IETALS			
Iron	ppm	■34	 	
Copper	ppm	■ 4	 	
Lead	ppm	■<1	 	
Tin	ppm	■ 0	 	
Aluminum	ppm	1	 	
Chromium	ppm	■<1	 	
Molybdenum	ppm	■<1	 	
Nickel	ppm	■<1	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	1	 	
Vanadium	ppm	0	 	
VOLVO			 	
ADDITIV	ES			
Calcium	ppm	■3649	 	
Magnesium	ppm	1 5	 	
Zinc	ppm	1509	 	
Phosphorus	ppm	1302	 	
Barium	ppm	□ 0	 	
Boron	ppm	107	 	
	-			



CRH CANADA GROUP INC.

P.O. BOX 5400 CONCORD, ON CA L4K 1B6 Contact: Dan Brown dan.brown@ca.crh.com T: F:

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is SAE 70W80 Wet Brake Transaxle Oil. Please confirm the oil type and grade, and specify the brand of the oil on your next sample.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: HOLCON
Unique No: 5620840
Signed: Wes Davis
Report Date: 14 Aug 2023



CONSTRUCTION EQUIPMENT





