

CONSTRUCTION EQUIPMENT

MARIPOSA HOMES 374165 VOLVO EC290B 80197 - HYDRAULIC SY

Sample No: VCP392221

Oil Type: **VOLVO SUPER HYDRAULIC OIL 46**

Job No: 374165





Strongco Equipment 5179 Fountain St N. Breslau, ON CA NOB 1M0 Contact: Nick Sanders nsanders@strongco.com T: (519)744-3518 F: (519)744-3284

Diagnosis

We recommend you service the filters on this component. Confirm the source of the lubricant being utilized for top-up/fill. We recommend an early resample to monitor this condition.All component wear rates are normal. There is a moderate amount of silt (particulates < 14 microns in size) present in the oil. Viscosity of sample indicates oil is within ISO 32 range, advise investigate. This plus the additive levels indicates that this is not the same brand, or type of oil as reported. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

CASKIT Depot: **Unique No:** 5629534 Signed: Kevin Marson **Report Date:** 18 Aug 2023

Contact/Location: Nick Sanders - CASKIT

0

2

ppm

ppm

ppm

Barium

Boron



CONSTRUCTION EQUIPMENT





GRAPHS

