

CONSTRUCTION EQUIPMENT NO UNIT 02580061 - HYDRAULIC SYSTEM



Sample No: VCP

Oil Type: NOT GIVEN

Job No:

VOLVO					
SAMPLE	INFORMATION				
Sample Number		VCP			
Sample Date		31 Aug 2023			
Machine Hours		0			
Oil Hours		0			
Oil Changed		N/A			
Sample Status		NORMAL			
VOLVO					
OIL CONDITION					
Visc @ 40°C	cSt	40.8			
CONTAM	ΙΝΔΤΙΩΝ				
Particles >4µm		2206			
Particles > 6µm		75			
Particles > 14µm		■ 9			
ISO 4406:1999 (c)		18/13/10			
Silicon	ppm	■4			
Sodium	ppm	1			
Potassium	ppm	■ <1			
WEAR M	FTALS				
Iron		<u> </u>			
Copper	ppm	2			
Lead	ppm	1			
Tin	ppm	0			
Aluminum	ppm	■ <1			
Chromium	ppm	■ <1			
Molybdenum	ppm	<1			
Nickel	ppm	■ 0			
Titanium	ppm	0			
Silver	ppm	0			
Manganese	ppm	<1			
Vanadium	ppm	0			
VOLVO					
ADDITIV	2				
Calcium	ppm	58			
Magnesium	ppm	4			
Zinc	ppm	423			
Phosphorus	ppm	358			
Barium	ppm	0			
Boron	ppm	<1			



Strongco Equipment 5179 Fountain St N. Breslau, ON CA N0B 1M0 Contact: Villamor Pingol vpingol@strongco.com T: (519)744-3518

F: (519)744-3518

Diagnosis

Resample at the next service interval to monitor. Please specify the component make and model with your next sample. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The condition of the oil is acceptable for the time in service.

Depot:CASKITUnique No:5633121Signed:Wes DavisReport Date:05 Sep 2023



CONSTRUCTION EQUIPMENT





GRAPHS

