Sample No: VCP380125
Oil Type: NOT GIVEN
Job No: 372935

VOLVO				
SAMPLE	E INFORMATIO	N		
Sample Number	•	VCP380125	 	
Sample Date		15 Aug 2023	 	
Machine Hours		1064	 	
Oil Hours		0	 	
Oil Changed		Not Changd	 	
Sample Status		NORMAL	 	
OIT CON	DITION			
Visc @ 40°C	cSt	59.1	 	
CONTAN	MINATION			
Silicon		<b>1</b> 0	 	
Sodium	ppm	<b>4</b>		
	ppm		 	
Potassium	ppm	<b>10</b>	 	
VOLVO				
WEAR N	METALS			
Iron	ppm	■103	 	
Copper	ppm	■20	 	
Lead	ppm	59	 	
Tin	ppm	<b>-&lt;1</b>	 	
Aluminum	ppm	<b>■&lt;1</b>	 	
Chromium	ppm	<b>1</b>	 	
Molybdenum	ppm	<1	 	
Nickel	ppm	<b>-&lt;1</b>	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	2	 	
Vanadium	ppm	0	 	
ADDITIV	VES			
Calcium	ppm	87	 	
Magnesium	ppm	1	 	
Zinc	ppm	75	 	
Phosphorus	ppm	436	 	
Barium	ppm	<1	 	
Boron	ppm	5	 	
20.011	PPIII			

## STRONGCO EQUIPMENT (CE)

1051 Heritage Rd.
Burlington, ON
CA L7L 4Y1
Contact: LLoyd Williams
lwilliams@strongco.com
T:
F: (905)643-6077

## Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. Please submit a sample of the new (unused) oil to establish a baseline. Metal levels are typical for a new component breaking in. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

 Depot:
 VOLVO0252

 Unique No:
 5633819

 Signed:
 Kevin Marson

 Report Date:
 07 Sep 2023



## **CONSTRUCTION EQUIPMENT**





## GRAPHS

