

Sample No: VCP333951

Oil Type: VOLVO AUTOMATIC TRANSMISSION FLUID AT102

Job No: 373347

NFORMATION				
•	VCP333951			
	31 Oct 2023			
	6131			
	0			
	Changed			
	NORMAL			
ITION				
	□27.7			
COL				
NATION				
NATION				
ppm	■ 4			
ppm	2			
ppm	■<1			
TALS				
ppm	■32			
ppm	■ 3			
ppm	■<1			
ppm	■ 0			
ppm	■ <1			
ppm	■ 0			
ppm	0			
ppm	■ <1			
ppm	0			
ppm	■<1			
ppm	■<1			
ppm	0			
2				
ppm	105			
ppm	1			
ppm	16			
ppm	214			
ppm ppm	□ 214 □ <1			
	ppm	VCP333951 31 Oct 2023 6131 0 Changed NORMAL ITION cSt	VCP333951 31 Oct 2023 6131 0	VCP333951



STRONGCO EQUIPMENT--CALGARY

7923 54TH STREET SE CALGARY, AB CA T2C 4R7 Contact: MAH COX MCOX@STRONGCO.COM T: (403)216-1010 F: (403)216-1016

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot:VOLVO3909Unique No:5670767Signed:Kevin MarsonReport Date:02 Nov 2023



CONSTRUCTION EQUIPMENT





