

# CONSTRUCTION EQUIPMENT 385346 VOLVO L 1 1 1 0 H 63 2 6 1 9 - REAR AXLE



Sample No: VCP381991
Oil Type: VOLVO WB 102

**Job No:** 385346

SAMPLE	INFORMATIO	N		
Sample Number		VCP381991	 	
Sample Date		30 Nov 2023	 	
Machine Hours		1058	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	<b>41.4</b>	 	
VOLVO				
CONTAN	MOITANIN			
Water	%	NEG	 	
Silicon	ppm	<b>23</b>	 	
Sodium	ppm	<b>2</b>	 	
Potassium	ppm	<b>2</b>	 	
VOLVO	AFTAL C			
WEAR M	AF I ALS			
Iron	ppm	<b>123</b>	 	
Copper	ppm	<b>■&lt;1</b>	 	
Lead	ppm	<b>□</b> <1	 	
Tin	ppm	<b>■</b> 0	 	
Aluminum	ppm	<b>1</b>	 	
Chromium	ppm	<b>■</b> 3	 	
Molybdenum	ppm	<b>11</b>	 	
Nickel	ppm	<b>-&lt;1</b>	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	<b>10</b>	 	
Vanadium	ppm	0	 	
	le le			
VOLVO	IFC			
ADDITIV	JE2			
Calcium	ppm	■3925	 	
Magnesium	ppm	■11	 	
Zinc	ppm	<b>1602</b>	 	
Phosphorus	ppm	<b>1296</b>	 	
Barium	ppm	<b>0</b>	 	
Boron	ppm	<u> </u>	 	
		_		



### STRONGCO EQUIPMENT (CE)

1051 Heritage Rd.
Burlington, ON
CA L7L 4Y1
Contact: Sue Hooton
shooton@strongco.com
T: (905)331-3835
F: (905)643-6077

#### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

 Depot:
 VOLVO0252

 Unique No:
 5694133

 Signed:
 Wes Davis

 Report Date:
 05 Dec 2023



## **CONSTRUCTION EQUIPMENT**





#### GRAPHS

