

## **CONSTRUCTION EQUIPMENT**

TREEWORKS 8000387220 VOLVO ECR 145E 316021 - REAR RIGH



Sample No: VCP392023

Oil Type: VOLVO PREMIUM GEAR OIL 80W-90 GL-5

**Job No:** 8000387220

VOLVO SAMDI F	INFORMATION			
	INI ONMATION	1/40000000	 <u> </u>	
Sample Number		VCP392023	 	
Sample Date		01 Dec 2023	 	
Machine Hours		977	 	
Oil Hours		977	 	
Oil Changed		N/A	 	
Sample Status		NORMAL	 	
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	<b>139</b>	 	
VOLVO	UNIA TION			
LONTAM	IINATION			
Water	%	NEG	 	
Silicon	ppm	<b>109</b>	 	
Sodium	ppm	<b>16</b>	 	
Potassium	ppm	<b>6</b>	 	
WEAR M	ETAI C			
	IC I ML7			
PQ		<b>603</b>	 	
Iron	ppm	■997	 	
Copper	ppm	<b>2</b>	 	
Lead	ppm	■0	 	
Tin	ppm	32	 	
Aluminum	ppm	■21	 	
Chromium	ppm	<b>18</b>	 	
Molybdenum	ppm	■0	 	
Nickel	ppm	■5	 	
Titanium	ppm	<1	 	
Silver	ppm	<1	 	
Manganese	ppm	<b>15</b>	 	
Vanadium	ppm	0	 	
VOLVO				
<b>ADDITIV</b>	Z			
Calcium	ppm	<b>27</b>	 	
Magnesium	ppm	<b>1</b> 4	 	
Zinc	ppm	<b>■</b> 39	 	
Phosphorus	ppm	242	 	
Barium		<b>242</b>	 	
Boron	ppm	2	 	
וטוטוו	ppm	2		



## STRONGCO EQUIPMENT INC.

55 ISNOR DRIVE, BURNSIDE INDUSTRIALPARK DARTMOUTH, NS CA B3B 1N6 Contact: Justin Hennigar jhennigar@strongco.com T: (902)468-5010

## Diagnosis

F: (902)468-2468

Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor. Metal levels are typical for a new component breaking in. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Depot:SHEDARUnique No:5694432Signed:Kevin MarsonReport Date:07 Dec 2023



## **CONSTRUCTION EQUIPMENT**





