



CONSTRUCTION EQUIPMENT

8000389895 VOLVO ECR305CL 110051 - COOLANT



Sample No: VCP393161
Oil Type: {unknown}
Job No: 8000389895



SAMPLE INFORMATION

Sample Number	VCP393161	---	---	---
Sample Date	15 Jan 2024	---	---	---
Machine Hours	15678	---	---	---
Sample Status	ABNORMAL	---	---	---

STRONGCO EQUIPMENT INC.

1640 ENTERPRISE ROAD
MISSISSAUGA, ON
CA L4W 4L4

Contact: Janice Cripps
jcripps@strongco.com
T: (905)565-3876
F: (905)670-2338



CONTAMINATION

Sand/Dirt	scalar	<input checked="" type="checkbox"/> NONE	---	---	---
Debris	scalar	<input checked="" type="checkbox"/> NONE	---	---	---
Precipitate	scalar	<input checked="" type="checkbox"/> NONE	---	---	---
Silt	scalar	<input checked="" type="checkbox"/> NONE	---	---	---

Diagnosis

We advise that you check all areas where contaminants can enter the system. We recommend that you drain the coolant from the component if this has not already been done. We recommend an early resample to monitor this condition.{not applicable} The sample contained a visible layer of foreign fluid contaminant, the origin and/or type of fluid is unknown. The coolant is no longer serviceable due to the presence of contaminants.

Depot: SHEMIS
Unique No: 5710238
Signed: Kevin Marson
Report Date: 23 Jan 2024



CONSTRUCTION EQUIPMENT



GRAPHS

Iron/Tin/Silver



Copper/Aluminum/Lead

