Sample No: VCP430191
Oil Type: VOLVO WB 102

Job No: 391698

VOLVO SAMPLE	E INFORMATION			
Sample Number		VCP430191	 	
•				
Sample Date		16 Jan 2024	 	
Machine Hours		2117	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
OIL CON	DITION			
Visc @ 40°C	cSt	40.0	 	
	CSt	40.0	 	
VOLVO				
CONTAN	MINATION			
Water	%	NEG	 	
Silicon	ppm	12	 	
Sodium	ppm	9	 	
Potassium	ppm	2	 	
i otassium	ррш			
VOLVO				
WEAR N	METALS			
Iron	ppm	203	 	
Copper	ppm	■ 3	 	
Lead	ppm	0	 	
Tin	ppm	■0	 	
Aluminum	ppm	1	 	
Chromium	ppm	4	 	
Molybdenum	ppm	2	 	
Nickel			 	
Titanium	ppm	0	 	
	ppm			
Silver	ppm	0	 	
Manganese	ppm	5	 	
Vanadium	ppm	0	 	
VOLVO			 	
ADDITIN	VES			
Calcium	ppm	■3742	 	
Magnesium	ppm	9	 	
Zinc	ppm	■ 1515	 	
Phosphorus	ppm	■1315 ■1315	 	
Barium	ppm	0	 	
Boron		■103	 	
DUIUII	ppm	103	 	

STRONGCO EQUIPMENT (CE)

1051 Heritage Rd.
Burlington, ON
CA L7L 4Y1
Contact: C. Carter
ccarter@strongco.com
T:

F: (905)643-6077

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO0252Unique No:5710557Signed:Wes DavisReport Date:17 Jan 2024



CONSTRUCTION EQUIPMENT





