

# CONSTRUCTION EQUIPMENT 392008 VOLVO L70H 624562 - FRONT AXLE



Sample No: VCP392848
Oil Type: VOLVO WB 102

**Job No:** 392008

SAMPLE	INFORMATIO	N		
Sample Number	•	VCP392848	VCP352971	 
Sample Date		23 Jan 2024	09 Nov 2022	 
Machine Hours		2023	1034	 
Oil Hours		2000	1034	 
Oil Changed		Changed	Changed	 
Sample Status		NORMAL	NORMAL	 
VOLVO	DITION			
OIL CON				
Visc @ 40°C	cSt	<b>50.1</b>	<b>40.5</b>	 
VOLVO				
CONTAN	MINATION			
Water	%	NEG	NEG	 
Silicon		MEG ■12	■10	 
Sodium	ppm	<b>■</b> 9	<b>9</b>	 
Potassium	ppm	<b>1</b>	2	 
Fotassium	ppm			 
VOLVO				
WEAR N	METALS			
Iron	ppm	<b>1</b> 4	■31	 
Copper	ppm	<b>-&lt;1</b>	<b>-</b> <1	 
Lead	ppm	<b>0</b>	<b>-</b> <1	 
Tin	ppm	<b>0</b>	<b>0</b>	 
Aluminum	ppm	<b>1</b>	<b>1</b>	 
Chromium	ppm	<b>-&lt;1</b>	<b>2</b>	 
Molybdenum	ppm	<b>2</b>	<b>1</b> 0	 
Nickel	ppm	<b>-&lt;1</b>	<b>-</b> <1	 
Titanium	ppm	0	<1	 
Silver	ppm	0	0	 
Manganese	ppm	<b>2</b>	■8	 
Vanadium	ppm	0	0	 
ADDITIV	IEC			
_				
Calcium	ppm	■3818	<b>4143</b>	 
Magnesium	ppm	<b>16</b>	<b>1</b> 11	 
Zinc	ppm	<b>1451</b>	<b>1651</b>	 
Phosphorus	ppm	<b>1183</b>	□1397	 
Barium	ppm	<b>0</b>	0	 
Boron	ppm	<b>106</b>	<b>116</b>	 



#### STRONGCO EQUIP (AB)

6 - 38403 BURNT LAKE TRAIL RED DEER COUNTY, AB CA T4S 2L4 Contact: Perry Doyle pdoyle@strongco.com T: (403)391-3520 F: (403)346-3487

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO9652Unique No:5720734Signed:Wes DavisReport Date:26 Jan 2024



## **CONSTRUCTION EQUIPMENT**





