

## CONSTRUCTION EQUIPMENT VINCI 392571 VOLVO EC950F 410078 - DIESEL ENGINE



Sample No: VCP394351

Oil Type: VOLVO ULTRA DIESEL ENGINE OIL 15W40 VDS-3

**Job No:** 392571

VOLVO				
SAMPLE	INFORMATION			
Sample Number	_	VCP394351	VCP347436	 
Sample Date		21 Feb 2024	14 Sep 2022	 
Machine Hours		3908	88	 
Oil Hours		0	0	 
Oil Changed		Changed	Changed	 
Sample Status		ABNORMAL	ABNORMAL	 
OIL CON	DITION			
Visc @ 100°C	cSt	<b>13.5</b>	<u> </u>	 
Oxidation (PA)	%	85	22	 
Oxidation (17)	70	05		
LUNTAN	IINATION			
			NEC	
Water	%	NEG	NEG	 
Soot %	%	■0.7	0	 
Nitration (PA)	%	88	27	 
Sulfation (PA)	%	72	34	 
Glycol	%	■0.0	0.0	 
Fuel	%	<1.0	0.5	 
Silicon	ppm	<u>^</u> 26	23	 
Sodium Potassium	ppm	<b>▲</b> 946 <b>■</b> 27	<b>4 2</b>	 
Potassium	ppm	<u> </u>	<u> </u>	 
VOLVO	IFTAL C			
WEAR M	IF I ALS			
Iron	ppm	<b>13</b>	■23	 
Copper	ppm	<b>■</b> 3	■8	 
Lead	ppm	<b>■</b> <1	<b>2</b>	 
Tin	ppm	<b>■</b> <1	■3	 
Aluminum	ppm	<b>5</b>	<b>3</b>	 
Chromium	ppm	<b>■&lt;1</b>	<b>=</b> <1	 
Molybdenum	ppm	<b>□74</b>	■80	 
Nickel	ppm	<b>2</b>	2	 
Titanium	ppm	0	<1	 
Silver	ppm	<b>0</b>	0	 
Manganese	ppm	0	2	 
Vanadium	ppm	0	0	 
VOLVO	IPC			
ADDITIV	EZ			
Calcium	ppm	■1596	■2151	 
Magnesium	ppm	<b>556</b>	63	 
Zinc	ppm	<b>1068</b>	<b>1122</b>	 
Phosphorus	ppm	<b>904</b>	■1061	 
Barium	ppm	■0	□0	 
Boron	ppm	<b>27</b>	<b>60</b>	 

## STRONGCO EQUIPMENT--CALGARY

7923 54TH STREET SE CALGARY, AB CA T2C 4R7 Contact: Tracey Lewin tlewin@strongco.com T: (403)216-1010 F: (403)216-1016

## Diagnosis

Check for low coolant level. We advise that you check the air filter, air induction system, and any areas where dirt may enter the component. The oil change at the time of sampling has been noted. We recommend you service the filters on this component. We recommend an early resample to monitor this condition.All component wear rates are normal. Water treatment chemicals present, indicating slow coolant leak. There is a moderate concentration of dirt present in the oil. Test for glycol is negative. The condition of the oil is acceptable for the time in service (see recommendation). The oil is no longer serviceable due to the presence of contaminants.

Depot:VOLVO3909Unique No:5734475Signed:Kevin MarsonReport Date:23 Feb 2024



## **CONSTRUCTION EQUIPMENT**





