

CONSTRUCTION EQUIPMENT

TRIPLE M METAL LP 396709 VOLVO EC380E 310885 - SWING DR

Sample No: VCP450404

Oil Type: VOLVO PREMIUM GEAR OIL 80W-90 GL-5

Job No: 396709

VOLVO					
SAMPLE	INFORMATION				
Sample Number		VCP450404	VCP252015	VCE115157	
Sample Date		08 Mar 2024	04 Feb 2020	31 Aug 2018	
Machine Hours		12206	4714	2222	
Oil Hours		0	0	0	
Oil Changed		Changed	Changed	Changed	
Sample Status		ABNORMAL	NORMAL	NORMAL	
OIL CON	DITION				
				- 100	_
Visc @ 40°C	cSt	134	■137	132	
VOLVO					
CONTAN	MINATION				
Water	%	<u> </u>	NEG	NEG	
Silicon	ppm	10	4	■8	
Sodium	ppm	■2	0	■3	
Potassium	ppm	1	<1	<1	
		_			
VOLVO	AFTALC				
WEAR N	IL I ALS				
Iron	ppm	242	■87	■ 194	
Copper	ppm	6	3	■ 14	
Lead	ppm		0	- <1	
Tin	ppm	■0	0	0	
Aluminum	ppm	■8	1	2	
Chromium	ppm	■3	1	2	
Molybdenum	ppm	0	0	- <1	
Nickel	ppm	■ <1	<1	<1	
Titanium	ppm	0	<1	0	
Silver	ppm	0	0	0	
Manganese	ppm	4	1	3	
Vanadium	ppm	0	0	0	
VOLVO					
ADDITIV	/ES				
Calcium	ppm	□ 39	118	1 9	
Magnesium	ppm	11	2	2	
Zinc	ppm	19	□ 60	1 5	
Phosphorus	ppm	1116	■1066	■ 1030	
Barium	ppm	0	0	1	
Boron	ppm	151	168	□ 152	



STRONGCO EQUIPMENT (CE)

1051 Heritage Rd.
Burlington, ON
CA L7L 4Y1
Contact: Sue Hooton
shooton@strongco.com
T: (905)331-3835
F: (905)643-6077

Diagnosis

We advise that you check for the source of water entry. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition. All component wear rates are normal. There is a moderate concentration of water present in the oil. The oil is no longer serviceable due to the presence of contaminants.

Depot:VOLVO0252Unique No:5746715Signed:Kevin MarsonReport Date:13 Mar 2024



CONSTRUCTION EQUIPMENT





