

Sample No: VCP449421
Oil Type: VOLVO WB 102

Job No: 400471

SAMPLE	INFORMATION			
Sample Number		VCP449421	VCP392808	
Sample Date		09 Apr 2024	07 Mar 2024	
Machine Hours		5295	4722	
Oil Hours		0	4000	
Oil Changed		Not Changd	Changed	
Sample Status		NORMAL	NORMAL	
Sumple Status		11011111111	TVOTATO LE	
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	42.6	42.5	
LUNTAN	MINATION			
_				
Water	%	NEG	NEG	
Silicon	ppm	10	1 8	
Sodium	ppm	■1	□4	
Potassium	ppm	■ <1	2	
VOLVO				
WEAR N	METALS			
Iron	ppm	■8	□28	
Copper	ppm	4	24	
Lead	ppm	0	- <1	
Tin	ppm	■0	0	
Aluminum	ppm	■<1	2	
Chromium	ppm	■0	<1	
Molybdenum	ppm	0	0	
Nickel	ppm	1	6	
Titanium	ppm	0	0	
Silver	ppm	0	0	
Manganese	ppm	0	1 0	
Vanadium	ppm	0	0	
Variation	ppiii	· ·	U	
VOLVO				
ADDITI\	IES			
Calcium	ppm	■3909	■3548	
Magnesium	ppm	<u> </u>	7	
Zinc	ppm	1583	1 499	
Phosphorus	ppm	■ 1275	1352	
Barium	ppm	0	1 0	
Boron	ppm	115	106	
	PP.11			



STRONGCO EQUIPMENT (CE)

1051 Heritage Rd.
Burlington, ON
CA L7L 4Y1
Contact: Sue Hooton
shooton@strongco.com
T: (905)331-3835
F: (905)643-6077

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO0252Unique No:5761400Signed:Wes DavisReport Date:11 Apr 2024



CONSTRUCTION EQUIPMENT





