

CONSTRUCTION EQUIPMENT 5307 - FRONT AXLE



Sample No: VCP392491
Oil Type: VOLVO WB 102

Job No:

VOLVO	MENDMATION			
	NFORMATION		_	
Sample Number		VCP392491	VCP298105	
Sample Date		02 Apr 2024	28 Aug 2021	
Machine Hours		13796	10039	
Oil Hours		2000	4000	
Oil Changed		Changed	Changed	
Sample Status		NORMAL	NORMAL	
OIL CONDI	TION			
Visc @ 40°C	cSt	41.9	E 30.0	
		_	□39.9	
Visc @ 100°C	cSt	■7.3		
Viscosity Index (VI)	Scale	138		
VOLVO				
CONTAMIN	NATION			
Water	%	NEG	NEG	
Silicon	ppm	13	12	
Sodium	ppm	7	8	
Potassium	ppm	1	2	
1 Ottassium	ppiii			
VOLVO				
WEAR ME	TALS			
Iron	ppm	7 3	■88	
Copper	ppm	■<1	1	
Lead	ppm	0	■0	
Tin	ppm	■0	■0	
Aluminum	ppm	1	2	
Chromium	ppm	1	1	
Molybdenum	ppm	0	< 1	
Nickel	ppm	■<1	- <1	
Titanium	ppm	0	0	
Silver	ppm	0	0	
Manganese	ppm	1	2	
Vanadium	ppm	0	<1	
ADDITIVE	7			
_		360 E	m 4047	
Calcium	ppm	■3605	□ 4047	
Magnesium	ppm	■14 ■1427	□12 □1707	
Zinc	ppm	■1437	□ 1707	
Phosphorus	ppm	■1174	1440	
Barium	ppm	■0	0	
Boron	ppm	100	1 30	



GREAT WEST EQUIPMENT

1600 KOSMINA ROAD, 123 L&A CROSS RD VERNON, BC CA V1T 8T2 Contact: Sarah Lawrence slawrence@gwequipment.com T: (866)627-2357 F: (250)549-3397

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:MARVERUnique No:5763681Signed:Kevin MarsonReport Date:23 Apr 2024



CONSTRUCTION EQUIPMENT





GRAPHS

