

## CONSTRUCTION EQUIPMENT VOLVO SD115B 236555 - DIESEL ENGINE



Sample No: VCP242478

Oil Type: VOLVO ULTRA DIESEL ENGINE OIL 15W40 VDS-3

Report Id: RIPTAM [WUSCAR] 04710405 (Generated: 12/20/2023 07:53:29) Rev: 1

Job No:

VOLVO				
SAMPLE	INFORMATION			
Sample Number	-	VCP242478	 	
Sample Date		24 Apr 2019	 	
Machine Hours		657	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
OIL COND	DITION			
Visc @ 100°C	cSt	<b>12.92</b>	 	
Oxidation (PA)	%	80	 	
VOLVO	INATION			
CONTAM	INATION			
Water	%	NEG	 	
Soot %	%	■ 0.3	 	
Nitration (PA)	%	71	 	
Sulfation (PA)	%	58	 	
Glycol	%	NEG	 	
Fuel	%	<1.0	 	
Silicon	ppm	<b>16</b>	 	
Sodium	ppm	<b>5</b>	 	
Potassium	ppm	<b>6</b>	 	
VOLVO				
<b>WEAR M</b>	ETALS			
Iron	ppm	■23	 	
Copper	ppm	■29	 	
Lead	ppm	<b>2</b>	 	
Tin	ppm	<b>■</b> 3	 	
Aluminum	ppm	<b>7</b>	 	
Chromium	ppm	<b>■</b> 3	 	
Molybdenum	ppm	<b>43</b>	 	
Nickel	ppm	<b>■</b> <1	 	
Titanium	ppm	<1	 	
Silver	ppm	<1	 	
Manganese	ppm	■3	 	
Vanadium	ppm	0	 	
VOLVO				
<b>ADDITIV</b>	ES			
Calcium	ppm	<b>1474</b>	 	
Magnesium	ppm	679	 	
Zinc	ppm	<b>1002</b>	 	
Phosphorus	ppm	■839	 	
Barium	ppm	□0	 	
Boron	ppm	<b>15</b>	 	



# RIPA AND ASSOCIATES 10149 FISHER AVENUE TAMPA, FL US 33619 Contact: ROBERT TURNER rturner@ripatampa.com T:

F:

#### Diagnosis

Resample at the next service interval to monitor. Metal levels are typical for a new component breaking in. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:RIPTAMUnique No:8591949Signed:Wes DavisReport Date:13 May 2019



### **CONSTRUCTION EQUIPMENT**





