

## CONSTRUCTION EQUIPMENT VOLVO A35G 340238 - GEARBOX



Sample No: VCP268783
Oil Type: {unknown}

Job No:

SAMPLE	INFORMATIO	N		
Sample Number		VCP268783	 	
Sample Date		21 Jan 2020	 	
Machine Hours		2714	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		ABNORMAL	 	
		ADITORIVIAL		
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	40.7	 	
VOLVO	MINATION			
_				
Water	%	NEG	 	
Silicon	ppm	<b>15</b>	 	
Sodium	ppm	<b>5</b>	 	
Potassium	ppm	<b>□</b> <1	 	
WEAR N	AFTAI S			
_				
ron	ppm	<b>■ 52</b>	 	
Copper	ppm	<u>▲</u> 341	 	
Lead 	ppm	<b>1</b>	 	
Tin 	ppm	■0	 	
Aluminum	ppm	<b>■</b> <1	 	
Chromium	ppm	<b>■</b> <1	 	
Molybdenum	ppm	<1	 	
Nickel	ppm	4	 	
Titanium 	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	2	 	
Vanadium	ppm	0	 	
VOLVO			 	
ADDITIV	/ES			
Calcium	_	3887	 	
Magnesium	ppm	6	 	
Zinc	ppm	1421	 	
Phosphorus	ppm	1246	 	
Pnospnorus Barium	ppm	0	 	
	ppm			
Boron	ppm	107	 	



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
8418 PALM RIVER ROAD
TAMPA, FL
US 33619
Contact: KENNY HANEY
khaney@flaglerce.com
T: (813)630-0077
F: (813)630-2233

## Diagnosis

No corrective action is recommended at this time. The oil change at the time of sampling has been noted. Resample at the next service interval to monitor. The copper level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO0093Unique No:8934078Signed:Don BaldridgeReport Date:25 Feb 2020



## **CONSTRUCTION EQUIPMENT**





