

## CONSTRUCTION EQUIPMENT VOLVO L110H 631301 - FRONT AXLE



Sample No: VCP274915
Oil Type: VOLVO WB 102

Job No:

| SAMPLI            | E INFORMATION |             |      |  |
|-------------------|---------------|-------------|------|--|
| Sample Number     |               | VCP274915   | <br> |  |
| Sample Date       |               | 03 May 2020 | <br> |  |
| Machine Hours     |               | 11442       | <br> |  |
| Oil Hours         |               | 2000        | <br> |  |
| Oil Changed       |               | Changed     | <br> |  |
| Sample Status     |               | ABNORMAL    | <br> |  |
|                   |               |             |      |  |
| OIL CON           | IDITION       |             |      |  |
| Visc @ 40°C       | cSt           | 41.2        | <br> |  |
| VISC @ 40 C       | CSt           | <b>41.2</b> | <br> |  |
| VOLVO             |               |             |      |  |
| CONTAI            | MINATION      |             |      |  |
| Silicon           | ppm           | <b>24</b>   | <br> |  |
| Sodium            | ppm           | <b>5</b>    | <br> |  |
| Potassium         | ppm           | <b>■</b> 0  | <br> |  |
|                   |               |             |      |  |
| WEAR              | METALS        |             |      |  |
| Iron              | ppm           | <b>1033</b> | <br> |  |
| Copper            | ppm           | <b>2</b>    | <br> |  |
| Lead              | ppm           | <b>1</b>    | <br> |  |
| Tin               | ppm           | <b>■</b> 0  | <br> |  |
| Aluminum          | ppm           | <b>1</b>    | <br> |  |
| Chromium          | ppm           | <b>19</b>   | <br> |  |
| Molybdenum        | ppm           | <b>14</b>   | <br> |  |
| Nickel            | ppm           | <b>5</b>    | <br> |  |
| Titanium          | ppm           | 1           | <br> |  |
| Silver            | ppm           | 0           | <br> |  |
| Manganese         | ppm           | <b>■26</b>  | <br> |  |
| Vanadium          | ppm           | <1          | <br> |  |
|                   |               |             | <br> |  |
| ADDITIV           | VES           |             |      |  |
| Calcium           | ppm           | <b>5307</b> | <br> |  |
|                   |               | <b>14</b>   | <br> |  |
| Magnesium         | ppm           | <b>1</b> 4  |      |  |
| Magnesium<br>Zinc |               | 2087        | <br> |  |
| •                 | ppm<br>ppm    |             | <br> |  |
| Zinc              | ppm           | <b>2087</b> |      |  |



## COVANTA

350 FLAKENBURG ROAD TAMPA, FL US 33619 Contact: SERVICE MANAGER

T: (813)684-5688 F:

## Diagnosis

The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition. Gear wear is indicated. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:COVTAMUnique No:9024609Signed:Don BaldridgeReport Date:12 May 2020



## **CONSTRUCTION EQUIPMENT**





