

CONSTRUCTION EQUIPMENT

9 VOLVO SD 115B 236555 - REAR LEFT FINAL DRIVE

Sample No: VCP301391

Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5

Job No: 63309

Phosphorus

Barium

Boron

ppm

ppm

ppm

1

■81

Report Id: RIPTAM [WUSCAR] 05172054 (Generated: 12/20/2023 07:56:01) Rev: 1

SAMPLE	INFORMATION			
Sample Number		VCP301391	VCP264115	
Sample Date		18 Jan 2021	09 Mar 2020	
Machine Hours		3328	2324	
Oil Hours		1000	1000	
Oil Changed		Changed	Changed	
Sample Status		NORMAL	ATTENTION	
OIL COND	ITION			
Visc @ 40°C	cSt	239	<u>▲</u> 135	
CONTAM	INATION			
Water	%	NEG	NEG	
Silicon	ppm	MEG ■5	■9	
Sodium	ppm	2	1 5	
Potassium	ppm	7	1	
1 Ottassiai II	ррпп	_ ′	1	
WEAR M	ETALS			
Iron	ppm	■88	241	
Copper	ppm	-<1	- <1	
Lead	ppm	0	□0	
Tin	ppm	■ 0	0	
Aluminum	ppm	-<1	< 1	
Chromium	ppm	■<1	2	
Molybdenum	ppm	1	0	
Nickel	ppm	0	<1	
Titanium	ppm	0	<1	
Silver	ppm	0	0	
Manganese	ppm	2	■8	
Vanadium	ppm	0	0	
VOLVO				
ADDITIVI	23			
Calcium	ppm	56	6 1	
Magnesium	ppm	■ 5	9	
Zinc	ppm	39	□ 53	

4

101



RIPA AND ASSOCIATES 10149 FISHER AVENUE TAMPA, FL US 33619

Contact: ROBERT TURNER rturner@ripatampa.com

T: F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot:RIPTAMUnique No:9347337Signed:Don BaldridgeReport Date:02 Feb 2021



CONSTRUCTION EQUIPMENT





