CONSTRUCTION EQUIPMENT 270306 VOLVO SD115B 236585 - HYDRAULIC SYSTEM

Sample No: VCP311893 **Oil Type:**

VOLVO

VOLVO SUPER HYDRAULIC OIL 46

Job No:

270306

	INFORMATION			
Sample Number	-	VCP311893	VCP278850	
Sample Date		11 Jun 2021	16 Nov 2020	
Machine Hours		1644	989	
Oil Hours		1644	989	
Oil Changed		Not Changd	Not Changd	
Sample Status		NORMAL	ATTENTION	
OIL COND	ITION			
Visc @ 40°C	cSt	43.2	43.8	
Acid Number (AN)) mg KOH/g	0.129	0.100	
CONTAM	INATION			
Water	%	NEG	NFG	

Water	%	NEG	NEG	
Particles >4µm		3676	5898	
Particles >6µm		325	681	
Particles >14µm		30	43	
ISO 4406:1999 (c)		19/16/12	20/17/13	
Silicon	ppm	3	2	
Sodium	ppm	2	0	
Potassium	ppm	■ <1	2	

WFAR MFTAI S

Iron	ppm	15	13	
Copper	ppm	1	3	
Lead	ppm	8	7	
Tin	ppm	0	<1	
Aluminum	ppm	0	0	
Chromium	ppm		 <1	
Molybdenum	ppm	 <1	0	
Nickel	ppm	0	<1	
Titanium	ppm	0	0	
Silver	ppm	0	0	
Manganese	ppm	 <1	< 1	
Vanadium	ppm	0	0	

ADDITI	VES			
Calcium	ppm	114	117	
Magnesium	ppm		0	
Zinc	ppm	87	75	
Phosphorus	ppm	394	444	
Barium	ppm	0	0	
Boron	ppm	2	0	

RIPA AND ASSOCIATES

10149 FISHER AVENUE TAMPA, FL US 33619 Contact: ROBERT TURNER rturner@ripatampa.com T: F:

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. The amount and size of particulates present in the system are acceptable. There is no indication of any contamination in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.


Depot: RIPTAM Unique No: 9565100 Signed: Don Baldridge Report Date: 01 Jul 2021

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Report Id: RIPTAM [WUSCAR] 05291145 (Generated: 03/13/2024 10:02:12) Rev: 1

Contact/Location: ROBERT TURNER - RIPTAM