Sample No: VCP330032

Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5

**Job No:** SWO840503 ACTION ENV

VOLVO	E INFORMATIO	W		
		<del></del> -		_
Sample Number		VCP330032		 
Sample Date		28 Feb 2022		 
Machine Hours		4627		 
Oil Hours		0		 
Oil Changed		Changed		 
Sample Status		SEVERE		 
VOLVO				
OIL CON	IDITION			
Visc @ 40°C	cSt	308		 
VISC @ 40 C	CSL	300		 
VOLVO				
<b>CONTAI</b>	MINATION			
Water	%	NEG		 
Silicon	ppm	<b>A</b> 359		 
Sodium	ppm	<b>6</b>		 
Potassium	ppm	<b>12</b>		 
WEAD	METALS			
_	ME I HL2			
Iron	ppm	<b>▲</b> 1504		 
Copper	ppm	<b>4</b>		 
Lead	ppm	<b>1</b>		 
Tin	ppm	■0		 
Aluminum	ppm	<b>39</b>		 
Chromium	ppm	<b>A</b> 26		 
Molybdenum	ppm	■3		 
Nickel	ppm	3		 
Titanium	ppm	3		 
Silver	ppm	<1		 
Manganese	ppm	<b>11</b>		 
Vanadium	ppm	<1		 
VOLVO				 
ADDITIV	VES			
Calcium	ppm	170		 
Magnesium	ppm	■ 170 ■ 13		 
Zinc	ppm	<b>■90</b>		 
Phosphorus	ppm	<b>1038</b>		 
Barium	ppm	<b>■</b> 0		 
Boron	ppm	■ 147		 
DOTOTI	ppiii	<b>17</b> 1	-	

ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
8418 PALM RIVER ROAD
TAMPA, FL
US 33619
Contact: KENNY HANEY
khaney@flaglerce.com
T: (813)630-0077

## Diagnosis

F: (813)630-2233

We advise that you check all areas where dirt can enter the system. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition. Gear wear is indicated. Elemental levels of silicon (Si) and aluminum (Al) indicate aluminasilicate (coarse dirt) ingress. The oil is no longer serviceable due to the presence of contaminants.

Depot:VOLVO0093Unique No:9883551Signed:Don BaldridgeReport Date:15 Mar 2022



## **CONSTRUCTION EQUIPMENT**





