

CONSTRUCTION EQUIPMENT
SW1003910 GILA CONC VOLVO EC200EL 314540 - REAR LEFT FIN

Sample No: VCP353841

Oil Type: **GEAR OIL SAE 80W90** Job No: **SW1003910 GILA CONC**

VOLVO	INFORMATION				
	INFURMATIUN				
Sample Number		VCP353841			
Sample Date		03 Jun 2022			
Machine Hours		590			
Oil Hours		0			
Oil Changed		Changed			
Sample Status		ABNORMAL			
VOLVO					
OIL CONDITION					
Visc @ 40°C	cSt	162			
		_			
VOLVO	INATION				
LUNIAM	INATION				
Water	%	NEG			
Silicon	ppm	16			
Sodium	ppm	■3			
Potassium	ppm	■ 3			
VOLVO					
WEAR M	ETAI C				
_		A ===			
Iron	ppm	△ 955			
Copper	ppm	1			
Lead	ppm	0			
Tin	ppm				
Aluminum	ppm	3			
Chromium	ppm	<u> </u>			
Molybdenum	ppm	2			
Nickel	ppm	<1			
Titanium	ppm	<1			
Silver	ppm	<1			
Manganese	ppm	13			
Vanadium	ppm	0			
ADDITIV	ES				
Calcium	ppm	7			
Magnesium	ppm	1			
Zinc	ppm	1 9			
Phosphorus	ppm	281			
Barium	ppm	■ <1			
Boron	ppm	1			
DOTOIT	ppiii	•			



ARNOLD MACHINERY COMPANY

4323 EAST WINSLOW AVENUE PHOENIX, AZ US 85040 Contact: RANDY PRZEKURAT randyp@arnoldmachinery.com T: F: (602)414-1904

Diagnosis

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor.Gear wear is indicated. All other metal levels are typical for a new component breaking in. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO6174 **Unique No:** 10010333 Signed: Don Baldridge Report Date: 13 Jun 2022



CONSTRUCTION EQUIPMENT





