

## CONSTRUCTION EQUIPMENT 8266 SECCRA VOLVO L70H 623679 - FRONT AXLE



Sample No: VCP358825
Oil Type: VOLVO WB 102
Job No: 8266 SECCRA

VOLVO				
SAMPLE	INFORMATIO	N		
Sample Number	_	VCP358825	 	
Sample Date		20 Jun 2022	 	
Machine Hours		7477	 	
Oil Hours		0	 	
Oil Changed		Not Changd	 	
Sample Status		ABNORMAL	 	
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	<b>41.5</b>	 	
VISC @ 40 C	CSt	41.5	 	
VOLVO				
CONTAN	MOITAMIN			
Water	%	NEG	 	
Silicon	ppm	<b>■</b> 5	 	
Sodium	ppm	<b>1</b>	 	
Potassium	ppm	<b>■</b> 0	 	
VOLVO				
WEAR N	METALS			
Iron	ppm	<b>18</b>	 	
Copper	ppm	<b>0</b>	 	
Lead	ppm	<b>=</b> <1	 	
Tin	ppm	<b>0</b>	 	
Aluminum	ppm	<b>■</b> <1	 	
Chromium	ppm	<b>-</b> <1	 	
Molybdenum	ppm	<b>1</b>	 	
Nickel	ppm	■0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	<b>1</b>	 	
Vanadium	ppm	0	 	
ADDITIV	731			
	_			
Calcium	ppm	<b>2976</b>	 	
Magnesium	ppm	<b>12</b>	 	
Zinc	ppm	<b>1265</b>	 	
Phosphorus	ppm	<b>1028</b>	 	
Barium	ppm	<b>0</b>	 	
Boron	ppm	■26	 	



#### **HOFFMAN EQUIPMENT - LIONVILLE**

120 GORDON DRIVE LIONVILLE, PA US 19341 Contact: JIM FEHR jim.fehr@hoffmanequip.com T: (610)363-9200 F: (610)594-0829

### Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. Moderate concentration of visible dirt/debris present in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO8879
Unique No: 10034489
Signed: Elizabeth Valachovic

Report Date: 17 May 2024

Contact/Location: JIM FEHR - VOLVO8879



# **CONSTRUCTION EQUIPMENT**





