

## **CONSTRUCTION EQUIPMENT**

SWA092698 GULF RENT VOLVO L30GS 3220275 - HYDRAULIC S

Sample No: VCP386710

Oil Type: AW HYDRAULIC OIL ISO 46

Job No: SWA092698 GULF RENT

SAMPLE II	NFORMATION				
Sample Number		VCP386710			
Sample Date		31 Oct 2022			
Machine Hours		5081			
Oil Hours		0			
Oil Changed		Changed			
Sample Status		SEVERE			
OIL CONDITION					
Visc @ 40°C	cSt	<b>43.9</b>			
Acid Number (AN)	mg KOH/g	■ 0.29			
VOLVO					
CONTAMII	NATION				
Water	%	1,27			
Silicon		■ 1.27 ■ 2			
Sodium	ppm				
Potassium	ppm	<b>2</b>			
Potassium	ppm	<b></b> 2			
VOLVO					
WEAR ME	TALS				
Iron	ppm	<b>■</b> 36			
Copper	ppm	■8			
Lead	ppm	<b>4</b>			
Tin	ppm	<b>■&lt;1</b>			
Aluminum	ppm	<b>■</b> 4			
Chromium	ppm	<b>1</b>			
Molybdenum	ppm	<b>■</b> 2			
Nickel	ppm	<b>■&lt;1</b>			
Titanium	ppm	0			
Silver	ppm	0			
Manganese	ppm	<b>■&lt;1</b>			
Vanadium	ppm	0			
ADDITIVE	۲				
Calcium	ppm	<b>■ 52</b>			
Magnesium	ppm	<b>3</b>			
Zinc	ppm	■ 358			
Phosphorus	ppm	■347			
Barium	ppm	<b>0</b>			
Boron	ppm	<b>2</b>			



#### **ALTA EQUIPMENT COMPANY**

5151 DR MARTIN LUTHER KING BLVD FORT MYERS, FL US 33905 Contact: TODD LARK tlark@altaequipfl.com

T:

F: (239)481-3302

### Diagnosis

We advise that you check for the source of water entry. Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition. There is too much water present in this sample to perform a particle count.All component wear rates are normal. Appearance is milky. There is a high concentration of water present in the oil. The AN level is acceptable for this fluid.

Depot:VOLVO0090Unique No:10205937Signed:Don BaldridgeReport Date:09 Nov 2022



# **CONSTRUCTION EQUIPMENT**





#### GRAPHS







