

CONSTRUCTION EQUIPMENT A09192 VOLVO A30G 740078 - WET DISC BRAKE



Sample No: VCP365707
Oil Type: MOBIL WB 102

Job No: A09192

TAMPI	E INFORMATION			
			1400000000	-
Sample Number		VCP365707	VCP288986	
Sample Date		10 Nov 2022	04 Nov 2020	
Machine Hours		4945	3630	
Oil Hours		1000	3630	
Oil Changed		Not Changd	Changed	
Sample Status		ABNORMAL	ABNORMAL	
VOLVO				
OIL CON	IDITION			
Visc @ 40°C	cSt	44.5	47.5	
V13C @ 40 C	CSt	— ++.3	77.5	
VOLVO				
CONTAI	MINATION			
Silicon	ppm	1 6	2 0	
Sodium	ppm	<u> </u>	<u> </u>	
Potassium	ppm	0	<1	
	PP		_	
VOLVO	METALC			
WEAK	METALS			
Iron	ppm	17	2 0	
Copper	ppm	187	<u>^</u> 227	
Lead	ppm	■3		
Tin	ppm	■<1	0	
Aluminum	ppm	■3	0	
Chromium	ppm		- <1	
Molybdenum	ppm	<1	<1	
Nickel	ppm		<1	
Titanium	ppm	<1	<1	
Silver	ppm	0	<1	
Manganese	ppm	<1	<1	
Vanadium	ppm	0	<1	
ADDITI	VFC			
_	_	2072	2004	
Calcium	ppm	2972	3001	
Magnesium	ppm	15	10	
Zinc	ppm	1297	1182	
Phosphorus	ppm	1026	1099	
Barium	ppm	0	0	
Boron	ppm	81	77	



K C CONSTRUCTION

1737 STOUT DRIVE IVYLAND, PA US 18974 Contact: DUKE D. duked@kcconstruct.com T: (267)784-7337 F: x:

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. The copper level is abnormal. All other component wear rates are normal. Moderate concentration of visible dirt/debris present in the oil. The condition of the oil is acceptable for the time in service.

Depot:KCCIVYUnique No:10227333Signed:Don BaldridgeReport Date:20 Nov 2022



CONSTRUCTION EQUIPMENT





