

CONSTRUCTION EQUIPMENT A09082 VOLVO A40G 341662 - B0GIE/CENTER AXLE



Sample No: VCP384280
Oil Type: MOBIL GO 102

Job No: A09082

IFODMATION				
NFORMATION				
	VCP384280	VCP278593		
	09 Nov 2022	09 Aug 2021		
	6440	5380		
	2000	1000		
	Not Changd	Not Changd		
	ABNORMAL	ATTENTION		
TION				
cSt	△ 55.8	<u> </u>		
	55.6			
NATIUN				
ppm	■8	□ 3		
ppm	5	4		
ppm	■<1	1		
TALS				
ppm	1024	■368		
ppm	■ 7	5		
ppm	■<1	- <1		
ppm	0	0		
ppm	■2	0		
ppm	13	4		
ppm	15	4		
ppm	4	2		
ppm	0	0		
ppm	0	<1		
ppm	24	□10		
ppm	0	0		
2				
ppm	57	□ 78		
ppm	2	1		
ppm	31	4 3		
ppiii				
ppm	2304	2191		
	2304 0	■2191 ■0		
	TION cSt NATION ppm ppm ppm ppm ppm ppm ppm p	VCP384280 09 Nov 2022 6440 2000 Not Changd ABNORMAL TION cSt	VCP384280 VCP278593 09 Nov 2022 09 Aug 2021 6440 5380 2000 1000 Not Changd Not Changd ABNORMAL ATTENTION TION CSt ▲ 55.8 ▲ 52.1 VATION PPM ● 5 ● 4 ppm ● 5 ● 4 ppm ● 7 ● 5 ppm ● 7 ● 5 ppm ● 1 ● 4 ppm ● 13 ● 4 ppm ● 15 ● 4 ppm ● 0 ● 0 ppm ● 2 ● 0 ppm ● 4 ● 2 ppm ● 0 ● 10 ppm ● 0 ● 0 ppm ● 24 ● 10 ppm ● 0 ● 0 ppm ● 24 ● 10 ppm ● 0 ● 0 ppm ● 0 ● 0	VCP384280 VCP278593 09 Nov 2022 09 Aug 2021 6440 5380 2000 1000 Not Changd ABNORMAL ATTENTION TION cSt 55.8 52.1 Ppm 8 3 ppm 5 4 ppm 5 4 ppm 7 5 ppm 7 5 ppm 0 0 ppm 13 4 ppm 15 4 ppm 0 ppm 0 ppm 0 ppm 0 ppm 0 ppm



K C CONSTRUCTION

1737 STOUT DRIVE IVYLAND, PA US 18974 Contact: DUKE D. duked@kcconstruct.com T: (267)784-7337 F: x:

Diagnosis

No corrective action is recommended at this time. We recommend an early resample to monitor this condition. Gear wear is indicated. All other component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. Confirm oil type.

Depot:KCCIVYUnique No:10227334Signed:Don BaldridgeReport Date:20 Nov 2022



CONSTRUCTION EQUIPMENT





