

CONSTRUCTION EQUIPMENT HORST VOLVO EC460CL 110503 - SWING DRIVE



Sample No: VCP348819

Oil Type: VOLVO SUPER GEAR OIL 75W-80-GO102

Job No: HORST

CAMPI	E INFORMATION				
		VCP348819	VCD240004	VCD140CF2	
Sample Number			VCP348804	VCP148652	
Sample Date		28 Jan 2023	27 Jan 2023	18 Dec 2015	
Machine Hours		9014	9014	3899	
Oil Hours		0	0	0	
Oil Changed		Changed	Changed	Not Changd	
Sample Status		ABNORMAL	NORMAL	NORMAL	
VOLVO					
OIL CON	IDITION				
Visc @ 40°C	cSt	145	148	168.3	
VOLVO	MINATION				
_					
Water	%	<u> </u>			
Silicon	ppm	■8	1 2	7	
Sodium	ppm	■2	1		
Potassium	ppm	■<1	- <1	2	
WEAR N	MFTAI S				
Iron	ppm	□ 358	□ 375	1 53	
Copper	ppm	11	15	9	
Lead		= <1	<1 < 1	1	
Tin	ppm	0	0	0	
Aluminum	ppm			<1	
	ppm	■ 1	□ 2 □ 5	2	
Chromium	ppm	_	_		
Molybdenum	ppm	2	2	0	
Nickel	ppm	0	0	<1	
Titanium	ppm	<1	<1	<1	
Silver	ppm	0	0	0	
Manganese	ppm	3	4	2	
Vanadium	ppm	0	0	0	
VOLVO					
ADDITIV	VES				
Calcium	ppm	118	162	221	
Magnesium	ppm	■28	27	10	
Zinc	ppm	69	□90	90	
Phosphorus	ppm	■1044	934	871	
Barium	ppm	1	1	<1	
Boron	ppm	139	156	80	
	ρρ				



HIGHWAY EQUIPMENT AND SUPPLY CO 200 BURKHOLDER DR. EPHRATA, PA US 17522 Contact: CHAD HERRON chad@hwyequip.com T: (717)859-3132 F: (717)859-2698

Diagnosis

We advise that you check for the source of water entry. The oil change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. Appearance is milky. There is a moderate concentration of water present in the oil. The condition of the oil is acceptable for the time in service.

Depot:INSEPHUnique No:10321072Signed:Don BaldridgeReport Date:03 Feb 2023



CONSTRUCTION EQUIPMENT





