

## **CONSTRUCTION EQUIPMENT**

3260B0 FLYWAY VOLVO EC250EL 314125 - REAR RIGHT FINAL DI

Sample No: VCP371178

Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5

**Job No:** 3260BO FLYWAY

VOLVO	INFORMATIO	V		
	INFURMATIU		 <u> </u>	
Sample Number		VCP371178	 	
Sample Date		13 Mar 2023	 	
Machine Hours		498	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		ABNORMAL	 	
OIL CON	NITION			
		-470	 <u> </u>	
Visc @ 40°C	cSt	<b>179</b>	 	
VOLVO				
CONTAM	IINATION			
Silicon	ppm	<u>^</u> 242	 	
Sodium	ppm	<b>■9</b>	 	
Potassium	ppm	<b>11</b>	 	
Otassiani	PPIII	• • • • • • • • • • • • • • • • • • • •		
VOLVO				
WEAR M	ETALS			
Iron	ppm	<u></u> ▲ 674	 	
Copper	ppm	<b>■&lt;1</b>	 	
Lead	ppm	<b>0</b>	 	
Tin	ppm	<b>■</b> <1	 	
Aluminum	ppm	<u> </u>	 	
Chromium	ppm	<u> </u>	 	
Molybdenum	ppm	<b>2</b>	 	
Nickel	ppm	<b>1</b>	 	
Titanium	ppm	6	 	
Silver	ppm	0	 	
Manganese	ppm	<b>9</b>	 	
Vanadium	ppm	<1	 	
ADDITIV	77			
	_			
Calcium	ppm	<b>9</b>	 	
Magnesium	ppm	<b>9</b>	 	
Zinc	ppm	<b>0</b>	 	
Phosphorus	ppm	■395	 	
Barium	ppm	■0	 	
Boron	ppm	<b>■</b> 0	 	



HIGHWAY EQUIPMENT AND SUPPLY CO 200 BURKHOLDER DR. EPHRATA, PA US 17522 Contact: CHAD HERRON chad@hwyequip.com T: (717)859-3132 F: (717)859-2698

## Diagnosis

We advise that you check all areas where dirt can enter the system. The oil change at the time of sampling has been noted. Resample at the next service interval to monitor. Gear wear is indicated. All other component wear rates are normal. Elemental levels of silicon (Si) and aluminum (Al) indicate alumina-silicate (coarse dirt) ingress. The condition of the oil is acceptable for the time in service.

Depot:INSEPHUnique No:10387712Signed:Don BaldridgeReport Date:24 Mar 2023



## **CONSTRUCTION EQUIPMENT**





