

## CONSTRUCTION EQUIPMENT 219138 ALTA USED VOLVO L180H 4243 - FRONT AXLE



Sample No: VCP403761

Oil Type: VOLVO WB 102

Job No: 219138 ALTA USED

SAMPLE	E INFORMATIO	N		
Sample Number		VCP403761	 	
Sample Date		30 Mar 2023	 	
Machine Hours		6983	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		ABNORMAL	 	
Sample Status		ADITORIVIAL		
VOLVO				
OIL CON	IDITION			
Visc @ 40°C	cSt	<b>158</b>	 	
CUNTAN	MINATION			
_	_			
Silicon	ppm	<b>6</b>	 	
Sodium	ppm	<b></b>	 	
Potassium	ppm	<b>0</b>	 	
VOLVO				
WEAR N	METALS			
Iron	ppm	<u></u> ▲ 538	 	
Copper	ppm	<b>4</b>	 	
Lead	ppm	<b>0</b>	 	
Tin	ppm	<b>■</b> 0	 	
Aluminum	ppm	<b>1</b>	 	
Chromium	ppm	<b>■8</b>	 	
Molybdenum	ppm	■2	 	
Nickel	ppm	<b>■&lt;1</b>	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	<b>6</b>	 	
Vanadium	ppm	0	 	
VOLVO			 	
ADDITIV	VES			
Calcium	ppm	922	 	
Magnesium	ppm	<b>20</b>	 	
Zinc	ppm	<b>501</b>	 	
Phosphorus	ppm	■963	 	
Barium	ppm	<b>-</b> <1	 	
Boron	ppm	■98	 	
		_		



ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC
9601 BOGGY CREEK RD
ORLANDO, FL
US 32824
Contact: Robert LaPlante
robert.laplante@altg.com
T: (407)508-9736
F: (407)659-8720

## Diagnosis

The oil change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor. Gear wear is indicated. There is no indication of any contamination in the oil. The oil viscosity is higher than normal. Confirm oil type.

Depot:VOLVO0096Unique No:10416419Signed:Don BaldridgeReport Date:11 Apr 2023



## **CONSTRUCTION EQUIPMENT**





